

FLOOD 2019 IN MALAPPURAM DISTRICT					
TALUK WISE FIELD STUDY IN AFFECTED AREAS					
LIST OF INHABITANTS TO BE SHIFTED TEMPORARLY - KONDOTTY TALUK					
SL NO	DATE	TEAM NO	VILLAGE	LOCATION	REMARKS
1	22-08-2019	9	Morayur	Varikkottupara	*Land slipping area . *Threat to 3 families hence to be evacuated temporary
2	22-08-2019	9	Morayur	Elikkottuparambu- Malabar aggregates	*Earth near to quarry liable to slide. *Strengthening/removal of earth needed. *Threat for human in heavy rain. *The permissios for quarry is to be rechecked. *30 families should be shifted during heavy rain.
3	22-08-2019	9	Pallikkal	Veettipurayi	*Unscientific method of ordinary earth removal. *The ordinary earth should be removed behind the house should be in terrace manner. *Protection wall should be constructed to prevent the sliding of soil. *One houuse to be evacuated during heavy rain.
4	22-08-2019	9	Pallikkal	Karaparambu Ward 2	*Unscientific method of ordinary earth removal by neighbour. *Retaining wall should be constructed for the saftey of the property of Pathumma and Soudabi. *Temporary evacuation.
5	22-08-2019	9	Pallikkal	Koorkanparambu	*Unscientific method of ordinary earth removal by neighbour. *Gabion structure should be constructed by consulting with the concerned Grama panchayath Engineer. *Land owner Kannanari Muhammed should be shifted during heavy rain.
6	22-08-2019	9	Vazhayur	Kodapram	*Unscientific method of ordinary earth removal. *The ordinary earth should be removed in terrace manner. *Retaining wall should be constructed. *One house to be evacuated during heavy rain.
7	26-08-2019	10	Cherukavu	Chenathala mala(Hussain city)	*An artificial rain water tank capacity of 36,00,000 litre on the up hill portion. *It is not safe and its construction is unscientific.It is threat for the inhabitants of the foot hill portion. *The tank should be emptied. *Moisture conservation pits should not be retained. * At Vaayanamoolaparambu -3 families of Vasu, Suresh, and Sivadasan to be temporely shifted .

