

FLOOD 2019 IN MALAPPURAM DISTRICT

TALUK WISE FIELD STUDY IN AFFECTED AREAS

LIST OF INHABITANTS TO BE SHIFTED TEMPORARLY - ERNAD TALUK

SL NO	DATE	TEAM NO	VILLAGE	LOCATION	REMARKS
1	21-08-2019	5	Malappuram	Kottakkunnu	*Cracks found. *Further incidents of land slip can be expected. *Inhabitants staying in north and west side should be evacuated during heavy rains.
2	22-08-2019	5	Pulpetta	Valamangalam Achadanmala	*Cracks formed in 10cm width on hill slope portion. *Rock fall. *70 families to be evacuated temporarily during heavy rain.
			Pookkottur	Kaippanakkode kunnu	*Threat for human in heavy rain. *Inhabitants staying in north,south and west side should be evacuated during heavy rains.
3	22-08-2019	5	Melmuri	Thachangode	*Land slip on house no.III/53k. *Evacuation of families from the down hill portion during heavy rain.
				Iriakulam	*Land slip on house no.111/311A. *Evacuation of families from the down hill portion during heavy rain.
4	24-08-2019	4	Vettilappara	Panambilavu-Kunurkandi	*Near moderate hazard zone area. *Land slide occurred in 2018. *Boulders visible up hill portion. *Threat to 16 families. *Families should be shifted during heavy rain.
5	26-08-2019	5	Melmuri, Anakayam, Malappuram	Aliyaparambu(Whole kunnu)	*Land slip occurred. *Un authorised quarries. *Water storage in the laterite quarry situated on the up hill portion.Probabilility of soil fall and rock fall. *Shifting of families from the down hill portion during heavy rain.
6	26-08-2019	5	Panakkad	Valiyangadi	*Visible cracks of size 50m length,30 to 40cm width and 1.50m depth in the land of Juma mazjid,Valiyangadi in the north south direction. *Evacuation of 12 families needed during heavy rain.

7	26-08-2019	5	Panakkad	Hagiyar palli	*Soil fall behind the house of Hafsath Manzoor,Athamanakath. *In heavy rains land slip can occur this family temporarily shifted during heavy rain.
8	26-08-2019	5	Panakkad	Kolar keramkundu	*Stream bank erosion. *Houses of Saithalavi thattayil,Avarankutty,Vadakkan partially damaged due to river bank erosion. *Not fit for stay to be shifted during heavy rain.
9	28-08-2019	5	Kavanur	Kottavumala	*Cracks visible. * Land slide down to 1.50 metre of the east west side of Kottavumala. *The families of down hill to be shifted during heavy rain.
10	28-08-2019	5	Kavanur	Ellur pidivalymala	*Water stored in latrite quarry on the up hill portion.Threat to the inhabitants of down hill. *Water stored in latrite quarry to be emptied. *Vertical cutting of the hill slope should be controlled.
Team members in this District					
Team No. 4 : Sri K.K.Dinesh, Surveyor, Soil conservation Office, Manjeri. Mob No. 9446404184					
Team No. 5 : Sri. Subeesh Thottiyil, Assistant Geologist, Manjeri. Mob No. 8281616379					
Sri.Muhammed Shukkoor, Surveyor, Soil conservation office, Perinthalmanna. Mob No.9895018468					
DISTRICT SOIL CONSERVATION OFFICER, MALAPPURAM AT MANJERI					