

## Annexure - II A (ii)


### Details of Vulnerable Areas to Flood ( Rural -Firka Level )

#### Low Vulnerable Areas

Firka Name : Chinnasalem  
 Block : Chinnasalem  
 Taluk : Chinnasalem  
 District : Villupuram

Details of Vulnerable Areas						
Sl.No	Types of Vulnerability in the area	Details of the Area	Inundation details - Water level (ft) /No.of days	Source of Flood	Street to be Used escape to relief centre	Distance to relief Centre (in Km)
1	2	3	4	5	6	7
1	Low Vulnerable	Chinnasalem PWD Tank Supply Channel	Nil	RAIN WATER	Nil	Does not aries

II. Details of Contacts		
Name of contact details		Contact Nos
Name of the Nodel Officer	Revenue Divisional Officer, Kallakurichi	9445000421
	Deputy Collector, Dharani Sugar Mill Kalayanallur	9994092207
Name of the Inter Department Team Leader	K.MANIKANDAN,spl tahsildar(CS), Chinnasalem.	9442122621
	R.MATHESWARAN,E.O.TOWN PANCHAYAT	7824058350
	TMT.SARANYA, DOCTOR	9940960046
	SHANMUGAM-INSPECTOR	9444175797
Nearest Police Station	Chinnasalem	04151-236238
Nearest Fire Station & Rescue Station	Chinnasalem	04151- 256101
Name of Taluk	Chinnasalem	04151-257400



## Annexure - II A (ii)

III. Analysis of Vulnerability (URBAN)		IV. Details of First Responders				
Details of Vulnerability		Place of Flooding	Location		Name	Contact No
		Location				
		Chinnasalam				
1. Source of Flooding		Chinnasalam Tank Supply Channel	Location			
2. Cause of Flooding ( Breach / Overflow/ Encroachment & etc..)		Overflow				
3. Rainfall Reacived in the Area (Heavy Down pour data which triggered the event with date)		Nil	Chinnasalam	1.	Krishnan	9486280469
4. Relief Centres Operated to tide over the Situations		Girls Government Higer Sec School		2.	Bhuvaneshwaran	9791867319
5. Number of persons evacuated and housed in Relief Camps		Nil		3.	Murugavel	9597228192
6. Number of days Relief Camps was in Operation		Nil		4.	Kiruba	9600554724
7. Works Taken up During Current Year		Nil		5.	Senthil	9626065645
a.	Temporary Measures taken to restore damaged portions in case of breaches	Damaged Portions are Restored				
b.	Permanent Measures taken to restore the damaged portions in case of breaches	Damaged Portions are Restored				
c.	Desilting Activites under taken	No incidents in last years				
8. Permanent measures identified to be undertaken to minimize the risks in Area. ( Diversion canel constructions of retaining wall, converstion of pipe culvert to box culvert etc...)		Does not Arised				

## Annexure - II A (ii)

### Details of Vulnerable Areas to Flood ( Rural -Firka Level )

#### Low Vulnerable Areas


Firka Name : Vadakkanandal  
 Block : Vadakkanadal  
 Taluk : Chinnasalem  
 District : Villupuram

#### Details of Vulnerable Areas

Sl.No	Types of Vulnerability in the area	Details of the Area	Inundation details - Water level (ft) /No.of days	Source of Flood	Street to be Used escape to relief Centre	Distance to relief Centre (in Km)
1	Low Vulnerable	Vadakkanandal Kalleri		Since all the anicut structures are located across the River & there is a fall to mitigate all the flood water in to the river, there are no inundations happening around here.		Does not arise
2	Low Vulnerable	Kachirayapalayam supply channel				

#### II. Details of Contacts

Sl.No	Name of contact details		Contact Nos
1	Name of the Nodel Officer	Revenue Divisional Officer, Kallakurichi	9445000421
		Deputy Collector, Dharani Sugar Mill Kalayanallur	9994092207
2	Name of the Inter Department Team Leader	1.S.RAMAMURTHI ,ZDT,Chinnasalem	7904971577
		2. MUTHU TOWN PANCHAYAT Vadakkanandal	8883100398
		3. Rajkumar - Inspector	9443396949
3	Nearest Police Station	KACHIRAYAPALAYAM	04151-234236
		Rajkumar - Inspector	9443396949
4	Nearest Fire Station & Rescue Station	Chinnasalem kallakurichi	04151-256101 04151-222101
5	Name of Taluk	Chinnasalem	04151-257400



## Annexure - II A (ii)

III. Analysis of Vulnerability (RURAL)				IV. Details of First Responders			
Details of Vulnerability		Place of Flooding		Location	Name	Contact No	
		Location 1	Location 2				
		Vadakkanandal	Kachirapalayam				
1. Source of Flooding		Vadakkanandal Kalleri	Kachirapalayam Supply Channel	<b>Location 1</b>			
2. Cause of Flooding ( Breach / Overflow/ Encroachment & etc..)		Breach	Overflow				
3. Rainfall Reacived in the Area (Heavy Down pour data which triggered the event with date)		-	-	<b>Vadakkanandal Kalleri</b>	1.	Murugapillai	9486280469
					2.	Angamuthu	9791867319
4. Relief Centres Operated to tide over the Situations		Boys Government Higer Sec School	Boys Government Higer Sec School		3.	Azhagesan	9597228192
					4.	Krishnan	9600554724
5. Number of persons evacuated and housed in Relief Camps		-	-		5.	Kaliyamoorthy	9626065645
6. Number of days Relief Camps was in Operation		-	-	<b>Location 2</b>			
7. Works Taken up During Current Year		-	-	<b>Kachirapalayam Supply Chennal</b>	1.	Arunachalam	9843177407
					2.	Kumar	9047712712
a. Temporary Measures taken to restore damaged portions in case of breaches		Damaged Portions are Restored	Damaged Portions are Restored		3.	Ayyadurai	9750145242
b. Permanent Measures taken to restore the damaged portions in case of breaches		Damaged Portions are Restored	Damaged Portions are Restored		4.	Hariselvam	9786360826
c. Desilting Activites under taken		No incidents in last years	No incidents in last years		5.	Periyasamy	9626403452
8. Permanent measures identified to be undertaken to minimize the risks in Area. ( Diversion canel constructions of retaining wall, conversion of pipe culvert to box culvert etc...)		Does Not Arised	Does Not Arised				