

Vulnerable Areas (Taluk wise) in Dindigul District

ABSTRACT

Sl. No.	Taluk	Very High vulnerability	High vulnerability	Moderate vulnerability	Low vulnerability	Total
1.	Dindigul West	0	0	1	16	17
2.	Dindigul East	0	2	0	7	9
3.	Nilakottai	0	0	2	5	7
4.	Natham	0	0	0	3	3
5.	Athoor	0	1	0	0	1
6.	Palani	0	3	0	3	6
7.	Oddanchatram	0	1	0	13	14
8.	Vedasandur	0	2	0	6	8
9.	Kodaikanal	0	2	0	0	2
	Total	0	11	3	53	67

1.Dindigul West Taluk

Sl. No	Name of the location	Name & Type of local body (Village Panchayat/Town Panchayat/Municipality and corporation	Reasons for Vulnerability
I.	Very High Vulnerability		
		NIL	
II.	High Vulnerability		
		NIL	
III.	Moderate Vulnerability		
1.	Athuppatty, H/o.Thadicombu, Dindigul west Taluk	Thadicombu Town Panchayat	Way side village of River and Due heavy flood in the past Year (1977)
IV.	Low Vulnerability		
1.	Lakshmananpatty, H/o. Agaram, Dindigul West Taluk	Agaram Town Panchayat	Due to heavy flood in the past Year (1977)
2.	Kiriampatty Colony, H/o. Agaram Dindigul West Taluk	Agaram Town Panchayat	Way side village of a river
3.	Purusanathy Undarpatty, H/o. Thadicombu Dindigul West Taluk	Thadicombu Town Panchayat	Way side village of River and Due heavy flood in the past Year (1977)
4.	Varattaru Andiyagoundanur, H/o. Thadicombu Dindigul West Taluk	Thadicombu Town Panchayat	Way side village of River and Due heavy flood in the past Year (1977)
5.	Muthanampatty, H/o. Kuttathupatty Dindigul West Taluk	Kuttathupatty Pt.,/ Village Panchayat	Due heavy flood in the past Year
6.	Ayyankulam, H/o.Pallapatty, Dindigul West Taluk	Dindigul Corporation	Due to heavy rain in whole Dindigul in 1977 the area was submerged in water.
7.	Sengulam, (Begam sahibanagar), H/o.Pallapatty Dindigul West Taluk	Pallapatty Pt., / Village Panchayat	Due to heavy rain in whole Dindigul in 1977 the area was submerged in water.
8.	Mungil kulam, (Pudupatty), H/o.Pallapatty Dindigul West Taluk	Pallapatty Pt., / Village Panchayat	Due to heavy rain in whole Dindigul in 1977 the area was submerged in water.
9.	Alankulam, H/o.Pallapatty Dindigul West Taluk	Pallapatty Pt., / Village Panchayat	Due to heavy rain in whole Dindigul in 1977 the area was submerged in water.
10.	Paraikulam (West Meenakshinayakkanpatty) H/o.Kurumbapatty, Dindigul West Taluk	Kurumbapatty Pt., / Village Panchayat	Due to heavy rain in whole Dindigul in 1977 the area was submerged in water.
11.	Rajakulam (Periyar Nagar Seelpadi), H/o.Seelpadi Dindigul West Taluk	Seelpadi Pt., / Village Panchayat	Marooned area
12.	Paraikulam (NS Nagar Seelpadi), H/o. Seelpadi Dindigul West Taluk	Seelpadi Pt., / Village Panchayat	Due to heavy rain in whole Dindigul in 1977 the area was submerged in water.

13.	Periyakulam , H/o. Seelpadi Dindigul West Taluk	Seelpadi Pt./ Village Panchayat	Due to heavy rain in whole Dindigul in 1977 the area was submerged in water.
14.	Maruthanikulam, (RM Colony) H/o. Chettinayakkanpatty (Town), Dindigul West Taluk	Dindigul Corporation	Due to heavy rain in whole Dindigul in 1977 the area was submerged in water.
15.	Mandaikulam H/o. Chettinayakkanpatty Dindigul West Taluk	Chettinayakkanpatty Pt., / Village Panchayat	Due to heavy rain in whole Dindigul in 1977 the area was submerged in water.
16.	Senkulam, H/o. Chettinayakkanpatty Dindigul West Taluk	Chettinayakkanpatty Pt., / Village Panchayat	Due to heavy rain in whole Dindigul in 1977 the area was submerged in water.

2.Dindigul East Taluk

Sl. No	Name of the location	Name & Type of local body (Village Panchayat/Town Panchayat/Municipality and corporation	Reasons for Vulnerability
I.	Very High Vulnerability		
		NIL	
II.	High Vulnerability		
1.	Theethampatti, H/o. Rajakkapatti, Dindigul East Taluk	Rajakkapatti Pt., / Village panchayat	Way side village of pond and heavy flood.
2.	NGO Colony, H/o. Balakrishnapuram Dindigul East Taluk	Balakrishnapuram Pt., / Village panchayat	Due to heavy rain overflow of water .
III.	Moderate Vulnerability		
		NIL	
IV.	Low Vulnerability		
1.	Markkampatti, Dindigul East Taluk	V.S.Kottai Pt., / Village panchayat	Dam, marooned area
2.	Koothampatti, Narivilampatti , H/o.Kambiliampatti, Dindigul East Taluk	Kambiliampatti Pt., / Village panchayat	Due to heavy flood in the past year/way side village of a river area
3.	Kallanpudur, H/o.Siluvathur, Dindigul East Taluk	Siluvathur Pt., / Village panchayat	Way side village of odai and heavy flood.
4.	Andivadan Chettiyur, H/o.Rahalapuram, Dindigul East Taluk	Rahalapuram Pt., / Village panchayat	Due to heavy flood in the past year.
5.	Aranmanikulam, Adianuthu, Dindigul East Taluk	Dindigul Corporation	Due to heavy rain overflow of water.
6.	Sadayampatti, Pudupatti, H/o.Senkuruchi, Dindigul East Taluk	Senkuruchi Pt., / Village panchayat	Due to heavy flood in the past year/way side village of a river area.
7.	Kodanginaickenpatti, H/o.Mullipadi, Dindigul East Taluk	Mullipadi Pt., / Village panchayat	In previous years of experience it is known as heavy rain spot.

3. Nilakottai Taluk

Sl. No	Name of the location	Name & Type of local body (Village Panchayat/Town Panchayat/Municipality and corporation	Reasons for Vulnerability
I.	Very High Vulnerability		
		NIL	
II.	High Vulnerability		
		NIL	
III.	Moderate Vulnerability		
1.	Anaipatty, H/o.Vilampatti, Nilakottai Taluk	Sithargalnatham Village Panchayat	It is located in River way side.
2.	S.Vadipatti H/o.Sithargalnatham, Nilakottai Taluk	Sithargalnatham Village Panchayat	way side village of a river
IV.	Low Vulnerability		
1.	Kottathu Ayyampalayam, H/o.Sivagnanapuram, Nilakottai Taluk	Sivagnapuram Pt.,	way side village of a river
2.	Bodiyagoundanpatti, Nilakottai Taluk	Bodiyagoundanpatti Pt.,	way side village of a river
3.	Lakshmipuram, H/o.Kulichettipatty, Nilakottai Taluk	Kulichettipatty Pt.,	way side village of a river
4.	Pallapatti(Mavur odai), Nilakottai Taluk	Pallapatti Pt.,	way side village of a river
5.	Nadakottai, Nilakottai Taluk	Nadakottai Pt.,	way side village of a river

4. Natham Taluk

Sl. No	Name of the location	Name & Type of local body (Village Panchayat/Town Panchayat/Municipality and corporation	Reasons for Vulnerability
I.	Very High Vulnerability		
		NIL	
II.	High Vulnerability		
		NIL	
III.	Moderate Vulnerability		
		NIL	
IV.	Low Vulnerability		
1.	Gandhinagar, Anna nagar, Natham Kovilpatti , Natham Village & taluk	Natham Town Panchayat	Thirumanimutharu River
2.	Ammapatty, H/o.Samuthirapatty, Natham Taluk	Samuthirapatty Pt., / Village panchayat	Thirumanimutharu River
3.	Melamettupatty, H/o.Chellapanaickenpatty, Natham Taluk	Chellapanaickenpatty Pt., / Village panchayat	KancharanKulam Kattiyakkaran Kulam

5. Athoor Taluk

Sl. No	Name of the location	Name & Type of local body (Village Panchayat/Town Panchayat/ Municipality and corporation	Reasons for Vulnerability
I.	Very High Vulnerability		
		NIL	
II.	High Vulnerability		
1.	Yenikkal, H/o.Manalur, Authoor Taluk	Manalur Pt., / Village panchayat	During 2015, due to heavy rain, caused landslide. Vehicular traffic affected and the road was set right by the Highways department.
III.	Moderate Vulnerability		
		NIL	
IV.	Low Vulnerability		
		NIL	

6. Palani Taluk

Sl. No	Name of the location	Name & Type of local body (Village Panchayat/Town Panchayat/Municipality and corporation	Reasons for Vulnerability
I.	Very High Vulnerability		
		NIL	
II.	High Vulnerability		
1.	Tamaraikulam, Palani Taluk	Tamarikulam Pt., / Village panchayat	It was affected by Patchaiaru, Porunthalaru rivers during the flood on the year 1993
2.	A.Kalyamputhur, Palani Taluk	A.Kalyamputhur Pt., / Village panchayat	It was damaged by patchaiaru, porunthalaru, shanmuganthi rivers during the flood pn 1993
3.	Periammapatti, Palani Taluk	Periammapatti Pt., / Village panchayat	This village has affected by Pachaiaru-Poruthalaru rivers on 1993
III.	Moderate Vulnerability		
		NIL	
IV.	Low Vulnerability		
1.	Balagamudram, Palani Taluk	Balagamudram Town Panchayat	This village not affected in any flood.
2.	Pushpathur, Palani Taluk	Pushpathur Pt, / Village panchayat	It was damaged by Amaravathi, river during the flood 1993
3.	Kanakkanpatty, Palani Taluk	Kanakkanpatty Pt., / Village panchayat	This village was affected by mappillainayakkar kulam, nallathangal odai and rain water from hills .

7. Oddanchatram Taluk

Sl. No	Name of the location	Name & Type of local body (Village Panchayat/Town Panchayat/Municipality and corporation	Reasons for Vulnerability
I.	Very High Vulnerability		
		NIL	
II.	High Vulnerability		
1.	Sindalavadanpatti, Oddanchatram Taluk	Sindalavadanpatti Pt., / Village panchayat	Due to Heavy Flood in way slide Village (Nallathangal River) of a river side at lower Area.
III.	Moderate Vulnerability		
		NIL	
IV.	Low Vulnerability		
1.	Javvadhupatti & Javvadhupatti pudur, Oddanchatram Taluk	Javvadhupatti Pt., / Village panchayat	Due to Heavy Flood, the low lying areas of the Nanganchi river Basin are affected.
2.	Idayakottai, Oddanchatram Taluk	Idayakottai Village Pt.,	Due to Heavy Flood in Nanganchi River, the NorthEast Portion of the Nanganchi Dam is Affected. So the low lying areas are to be affected.(302,329)
3.	Veriappur, Oddanchatram Taluk	Veriappur Village Pt.,	Due to Heavy Flood, the low lying areas of the river Basin are affected.
4.	Virupatchi, Oddanchatram Taluk	Virupatchi Village Pt.,	Due to Heavy Flood in way slide Village (Nanganchi River) of a river side at lower Area.
5.	Arasappapillaipatti, Oddanchatram Taluk	Arasappapillaipatti Village Pt.,	Due to Heavy Flood in way slide Village (Nanganchi River) of a river side at lower Area.
6.	Kaveriammpatti, Oddanchatram Taluk	Kaveriammpatti Village Pt.,	Due to Heavy Flood in way slide Village (Nanganchi River) of a river side at lower Area.
7.	Manjanaickenpatti, Oddanchatram Taluk	Manjanaickenpatti Village Pt.,	Due to Heavy Rain in Palani Hills and Flood in Both sides of Low lying areas in Nallathagal Odai. (20.10.2014)
8.	Boduvarpatti, Oddanchatram Taluk	Boduvarpatti Village Pt.,	Due to Heavy Rain in Palani Hills and Flood in Both sides of Low lying areas in Nallathagal Odai. (20.10.2014)
9.	Kothayam, Oddanchatram Taluk	Kothayam Village Pt.,	Due to Heavy Rain in Palani Hills and Flood in Both sides of Low lying areas in Nallathagal Odai. (20.10.2014)
10.	Porulur, Oddanchatram Taluk	Porulur Village Pt.,	Due to Heavy Rain in Palani Hills and Flood in Both sides of Low lying areas in Nallathagal Odai. (20.10.2014)
11.	Appipalayam, Oddanchatram Taluk	Appipalayam Village Pt.,	Due to Heavy Rain in Palani Hills and Flood in Low lying areas of Nallathagal Odai on 20.10.2014
12.	Pallappanpatti pudur, Oddanchatram Taluk	Pallappanpatti Village Pt.,	Due to Heavy Rain in Palani Hills and Flood in Low lying areas of Nallathagal Odai on 20.10.2014
13.	Paruthiyur, Oddanchatram Taluk	Paruthiyur Village Pt.,	Due to Heavy Rain in Palani Hills and Flood in Low lying areas of Nallathagal Odai on 20.10.2014

8. Vedasandur Taluk

Sl. No	Name of the location	Name & Type of local body (Village Panchayat/Town Panchayat/Municipality and corporation	Reasons for Vulnerability
I.	Very High Vulnerability		
		NIL	
II.	High Vulnerability		
1.	Rajagopalapuram, Vedasandur Village & Taluk	Vedasandur Town Panchayat	GUDAGANAARU RIVER - FLASH FLOOD
2.	Nagakonur, Vedasandur Village & Taluk	Vedasandur Town Panchayat	GUDAGANAARU RIVER - FLASH FLOOD
III.	Moderate Vulnerability		
		NIL	
IV.	Low Vulnerability		
1.	Thummalakundu, Vedasandur Taluk	Thummalakundu Village Pt.,	Marooned Area
2.	Kulathur, Vedasandur Taluk	Kulathur Village Pt.,	SANTHANAVARTHINI RIVER - FLASH FLOOD
3.	Kalvarpatti, Vedasandur Taluk	Kalvarpatti Village Pt.,	GUDAGANAARU RIVER - FLASH FLOOD
4.	Paalapatty, Vedasandur Taluk	Paalapatty Village Pt.,	GUDAGANAARU RIVER - FLASH FLOOD
5.	Koombur, Vedasandur Taluk	Koombur Village Pt.,	GUDAGANAARU RIVER - FLASH FLOOD
6.	Thirukooranam, Vedasandur Taluk	Thirukooranam Village Pt.,	GUDAGANAARU RIVER - FLASH FLOOD

9. Kodaikanal Taluk

Sl. No	Name of the location	Name & Type of local body (Village Panchayat/Town Panchayat/Municipality and corporation	Reasons for Vulnerability
I.	Very High Vulnerability		
		NIL	
II.	High Vulnerability		
1.	Savarikkadu, H/o. Vadagouchi, Kodaikanal Taluk	Vadagouchi Village Pt.,	Landslide
2.	Dumdum Parai near, H/o.Poolathur, Kodaikanal Taluk	Poolathur Village Panchayat	Landslide
III.	Moderate Vulnerability		
		NIL	
IV.	Low Vulnerability		
		NIL	