## FLOOD 2019 IN MALAPPURAM DISTRICT

## TALUK WISE FIELD STUDY IN AFFECTED AREAS

## LIST OF INHABITANANTS TO BE SHIFTED PERMANANTLY - KONDOTTY TALUK

SL NO	DATE	TEAM NO	VILLAGE	LOCATION	REMARKS
1	22-08-2019	9	Nediyiruppu	NH Colony	*Land slip behind the plot of Viswanathan he has to be evacuated permanently.
2	24-08-2019	10	Cherukavu	Aikkarapady, Vennayur -AUPB School.	*Unscientific removal of earth.  *Threat to school building and lives of students due to land slip.  *Need strengthening of area by concrete retaining wall in the north side and formation of terraces in the east side.
3	26-08-2019	10	Chelembra	Chekkumadukunnu	*A laterite block is situated on the top of the hillock causing threat to Yesudasan's House.  * Yesudasan should be evacuated. After that that laterite cutting should be terraced based on the guidance from Geology and Reveune Departments.

DISTRICT SOIL CONSERVATION OFFICER, MALAPPURAM AT MANJERI