

TANK PARTICULARS

District Rural Development Agency

Name of the District : Theni

Sl. No	Name of the Block	No. of tank
1	Andipatty	113
2	K.Myladumparai	3
3	Periyakulam	3
4	Theni	70
5	Bodinayakkanur	42
6	Chinnamanur	81
7	Uthamapalayam	29
8	Cumbum	3
		344

TANK PARTICULARS

District Rural Development Agency

Name of the District : Theni

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/ needs repairs / to be checked)	Date by which repair will be completed
	Andipatty Blcok									
1	Ammatchiapuram	Ammatchiapuram Oorani	0.36	Yes	0.24	Agricultural land	15.11.2018	Not started	Need To Repair	30.11.18
2	Anuppapatti	Mottaiyan Kulam	0.56	No	Nil	Nil	Nil	Nil	Good	Nil
3	Anuppapatti	Ayya goundar Kulam	0.56	No	Nil	Nil	Nil	Nil	Good	Nil
4	Anuppapatti	Pandian Kulam	0.48	Yes	0.48	Agricultural land	15.11.2018	Not started	Need To Repair	30.11.18
5	Anuppapatti	Vannan kulam	0.42	No	Nil	Nil	Nil	Nil	Good	Nil
6	Bodithasanpatti	Maniya karanpatty kilavi Kulam	0.42	No	Nil	Nil	Nil	Nil	Good	Nil
7	Bodithasanpatti	Bodithasanpatti Oorani	0.36	No	Nil	Nil	Nil	Nil	Good	Nil
8	Ethakoil	Samy kannu Oorani	0.57	Yes	0.35	Agricultural land	17.12.2018	Not start	Need To Repair	02.01.19
9	Ethakoil	Sithayagoundan oorani	0.36	No	Nil	Nil	Nil	Nil	Good	Nil

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
10	Ethakoil	Thirumamani Kulam	0.42	No	Nil	Nil	Nil	Nil	Good	Nil
11	Ethakoil	Mayappan Kulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
12	Ethakoil	Samathoppu Kulam	0.36	Yes	0.36	Agricultural land	17.12.2018	Not started	Need To Repair	02.01.19
13	Ethakoil	Sini Kulam	0.55	No	Nil	Nil	Nil	Nil	Good	Nil
14	Ethakoil	Vannan kulam	0.50	No	Nil	Nil	Nil	Nil	Good	Nil
15	Ethakoil	Alamukka Kulam	0.50	No	Nil	Nil	Nil	Nil	Good	Nil
16	Ethakoil	Pillai Kulam	0.28	No	Nil	Nil	Nil	Nil	Good	Nil
17	kanniyappapillai patti	Muthaian Oorani	1.60	No	Nil	Nil	Nil	Nil	Good	Nil
18	kanniyappapillai patti	Chinna kulam	2.58	No	Nil	Nil	Nil	Nil	Good	Nil
19	Kathirnarasingapuram	Panikar Oorani	0.16	No	Nil	Nil	Nil	Nil	Good	Nil
20	Kothaloothu	Vasavan kulam	0.32	No	Nil	Nil	Nil	Nil	Good	Nil
21	Kothaloothu	Maravapatty Oorani	0.37	No	Nil	Nil	Nil	Nil	Good	Nil

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
22	Kothapatti	pulvetikulam	0.89	No	Nil	Nil	Nil	Nil	Good	Nil
23	Kothapatti	andigunder oorani	0.36	No	Nil	Nil	Nil	Nil	Good	Nil
24	Kothapatti	kurumbar oorani	0.42	No	Nil	Nil	Nil	Nil	Good	Nil
25	Kovilpatti	Karattupatti Kulam	0.36	No	Nil	Nil	Nil	Nil	Good	Nil
26	Kovilpatti	Muthanampatty Oorani	0.86	No	Nil	Nil	Nil	Nil	Good	Nil
27	Marikundu	Bommaiasamy Kulam	6.27	No	Nil	Nil	Nil	Nil	Good	Nil
28	Marikundu	Malaiya Samy kulam	1.20	No	Nil	Nil	Nil	Nil	Good	Nil
29	Marikundu	Arasu marathu Kulam	0.80	No	Nil	Nil	Nil	Nil	Good	Nil
30	Marikundu	Eachi Periyayakkar Oorani	0.60	Yes	0.50	Agricultural land	03.01.2019	Not started	Need To Repair	18.01.19
31	Mottanuthu	Vandi Pathai Kulam	0.80	No	Nil	Nil	Nil	Nil	Good	Nil
32	Mottanuthu	Kandasamy Kulam	0.60	Yes	0.45	Agricultural land	21.01.2019	Not started	Need To Repair	07.02.19
33	Mottanuthu	Thopura Kulam -	0.75	No	Nil	Nil	Nil	Nil	Good	Nil

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
34	Mottanuthu	Koppaiampatti - kulam Oorani	1.90	No	Nil	Nil	Nil	Nil	Good	Nil
35	Mottanuthu	Nallamudipatti Oorani	0.60	No	Nil	Nil	Nil	Nil	Good	Nil
36	Mottanuthu	Nagalagoundanpatti -	1.08	Yes	0.78	Agricultural land	21.01.2019	Not started	Need To Repair	07.02.19
37	Okkarai Patti	Nettucheri kulam	4.25	No	Nil	Nil	Nil	Nil	Good	Nil
38	Okkarai Patti	Kanimar Oorani	0.60	No	Nil	Nil	Nil	Nil	Good	Nil
39	Okkarai Patti	Mayana oorani	0.80	No	Nil	Nil	Nil	Nil	Good	Nil
40	Okkarai Patti	Nimalkulam Oorani	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
41	Okkarai Patti	Veluchamy Puram - Alamarathu	0.60	No	Nil	Nil	Nil	Nil	Good	Nil
42	Palacombai	Pathai Kulan Oorani	1.20	No	Nil	Nil	Nil	Nil	Good	Nil
43	Palacombai	Pkulam Oorani	0.70	No	Nil	Nil	Nil	Nil	Good	Nil
44	Palacombai	Koppiya Kulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
45	Palacombai	Sali Kulam Karuppiam Kulam	0.80	No	Nil	Nil	Nil	Nil	Good	Nil

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
46	Palayakottai	Pinki Kulam	0.36	No	Nil	Nil	Nil	Nil	Good	Nil
47	Palayakottai	Kumaran Kulam	0.38	No	Nil	Nil	Nil	Nil	Good	Nil
48	Pichampatti	Pichampatty Vudaku Oorani	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
49	Pichampatti	Chenmayakanoorani	0.50	No	Nil	Nil	Nil	Nil	Good	Nil
50	Pullimancombai	Perumal thottam	0.52	No	Nil	Nil	Nil	Nil	Good	Nil
51	Pullimancombai	Raja nilam oorani	0.82	No	Nil	Nil	Nil	Nil	Good	Nil
52	Pullimancombai	Thempatti Thevar Colony oorani	0.92	No	Nil	Nil	Nil	Nil	Good	Nil
53	Pullimancombai	Rajapan Kotai oorani	0.60	No	Nil	Nil	Nil	Nil	Good	Nil
54	Pullimancombai	Moonandipatti Oorani	1.00	No	Nil	Nil	Nil	Nil	Good	Nil
55	Pullimancombai	p.p kulam	1.00	No	Nil	Nil	Nil	Nil	Good	Nil
56	Rajagopalanpatty	Vellamaramu oorani	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
57	Rajakkalpatti	Nattamai Kulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
58	Rajakkalpatti	Salai Maramu Kulam	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
59	Rajakkalpatti	Sengulam	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
60	Rajakkalpatti	Theppakulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
61	Rajakkalpatti	Aavarathi Oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
62	Rajakkalpatti	Ayyammai Oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
63	Rajakkalpatti	Muthuvel Oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
64	Rajakkalpatti	Elanthai Kulam	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
65	Rajakkalpatti	Veerachari Kulam	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
66	Rajakkalpatti	Pethinayakar Oorani	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
67	Rajakkalpatti	kodiyammal Oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
68	Rajakkalpatti	Pusari oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
69	Rajakkalpatti	Samiyan oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
70	Rajadhani	Malamanjinayakka npatty	0.40	Yes	0.40	Agricultural land	03.02.2019	Not started	Need To Repair	18.02.19
71	Rajadhani	Sevanilayam oorani	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
72	Rajadhani	Sundarajapuram Oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
73	Ramakrishnapuram	Aravankulam	0.64	No	Nil	Nil	Nil	Nil	Good	Nil
74	Ramakrishnapuram	Vannan Oorani	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
75	Rangasamudram	Natchiarapuram Oorani	0.80	No	Nil	Nil	Nil	Nil	Good	Nil
76	Rangasamudram	Rengasamuthiram kulam oorani	1.20	No	Nil	Nil	Nil	Nil	Good	Nil
77	Rangasamudram	Lakshmi Puram Oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
78	Rangasamudram	Kurumbapatti oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
79	Shanmugasundrapuram	Karisalpatti Oorani	0.28	No	Nil	Nil	Nil	Nil	Good	Nil
80	Shanmugasundrapuram	Muthusangilipatti oorani	1.20	No	Nil	Nil	Nil	Nil	Good	Nil
81	Shanmugasundrapuram	S.Spuram Kovil Oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
82	Shanmugasundrapuram	Asaripatty Kulam	8.14	No	Nil	Nil	Nil	Nil	Good	Nil
83	Shanmugasundrapuram	S. Renganathapuram	1.20	No	Nil	Nil	Nil	Nil	Good	Nil
84	Sittharpati	Puthukulam	0.60	No	Nil	Nil	Nil	Nil	Good	Nil
85	Sittharpati	Rengammal Kulam	0.60	No	Nil	Nil	Nil	Nil	Good	Nil
86	Sittharpati	Paila Kulam	0.60	No	Nil	Nil	Nil	Nil	Good	Nil
87	Sittharpati	Manthai kulam	0.60	No	Nil	Nil	Nil	Nil	Good	Nil
88	T.Subbulapuram	Kuuan Kulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
89	T.Subbulapuram	kuruban kulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
90	T.Subbulapuram	parai kulam	4.00	No	Nil	Nil	Nil	Nil	Good	Nil
91	T.Subbulapuram	Pula Kulam	2.00	No	Nil	Nil	Nil	Nil	Good	Nil
92	Thimmarasanaickanur	Kombai Perumal Kovil Kulam	0.40	Yes	0.25	Agricultural land	03.02.2019	Not started	Need To Repair	18.02.19
93	Thimmarasanaickanur	Amman Kulam	0.20	No	Nil	Nil	Nil	Nil	Good	Nil

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
94	Thimmarasanaickanur	Neeranikkan Kulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
95	Thimmarasanaickanur	Oothalaiyuthu Oorani	0.45	No	Nil	Nil	Nil	Nil	Good	Nil
96	T.Rajagopalanpatti	Silukkuvarpatty kulam	2.14	No	Nil	Nil	Nil	Nil	Good	Nil
97	Thimmarasanaickanur	Pillaimugampatti Samikulam	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
98	Thirumalapuram	Cylone Colony Kulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
99	Thirumalapuram	G Kallupatty kulam	2.00	No	Nil	Nil	Nil	Nil	Good	Nil
100	Thirumalapuram	Pandhuvar Patti Kulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
101	Thirumalapuram	Panduvar patti West Kulam	0.36	No	Nil	Nil	Nil	Nil	Good	Nil
102	Theppampatti	manthai kulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
103	Theppampatti	West kulam	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
104	Thekkampatti	Muthiveran Panikan Oorani	0.40	No	Nil	Nil	Nil	Nil	Good	Nil
105	Thekkampatti	Gopalnayakar Oorani	2.00	No	Nil	Nil	Nil	Nil	Good	Nil

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
106	Thekkampatti	Govindappan Nayakar Oorani	0.20	No	Nil	Nil	Nil	Nil	Good	Nil
107	Thekkampatti	Aranmanai Kanmai	8.83	No	Nil	Nil	Nil	Nil	Good	Nil
108	G.Usilampatti	Manthai Kulam Oorani	0.3	No	Nil	Nil	Nil	Nil	Good	Nil
109	G.Usilampatti	Munthiri Thoppu Oorani	0.2	No	Nil	Nil	Nil	Nil	Good	Nil
110	G.Usilampatti	Vannan kulam	0.4	No	Nil	Nil	Nil	Nil	Good	Nil
111	G.Usilampatti	Ramalingagoundar Patti	0.4	No	Nil	Nil	Nil	Nil	Good	Nil
112	G.Usilampatti	Ramalingapuram East oorani	0.4	No	Nil	Nil	Nil	Nil	Good	Nil
113	G.Usilampatti	Ramalingapuram Kanimar Oorani	0.4	No	Nil	Nil	Nil	Nil	Good	Nil
K.Myladumparai Blcok										
114	Varusanadu	Panjanthanki Kanmai	25.90.0 Acres	Yes	25.9	Agri	-	Court case pending W.P.13118/ of 2017	Good	-
115	Manthisunai-Moolakkadai	Santheneri kanmai	32.76 Acres	Yes	10.26	Agri	-	Court case pending W.P.(MD) 2517/ of 2018	Good	-

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
116	Thangammalpuram	Kovilparai Kanmai	13.41.5	-	-	Agri	2015-16	-	Good	-
Periyakulam Blcok										
117	Vadaputhupatty	Matthiya kowndar Orani	0.40.0	Yes	0.40.0	Agri Culture	-	-	Needs Repair	31.10.18
118	Vadaputhupatty	Jakkam Reddy Orani	0.40.0	Yes	0.40.0	Agri Culture	-	-	Good	-
119	D.Vadipatty	Kuvan Orani	0.40.0	Yes	0.40.0	House	-	-	Needs Repair	310.10.18
Theni Blcok										
120	Ambasamudram	AGAMT ooranie	0.98	No		-	-	-	Good	-
121	Aranmanaippudur	Pudukulam Odai ooranie	0.73	No		-	-	-	Good	-
122	Aranmanai pudur @ Pallapatti	Odai ooranie	0.55	No		-	-	-	Good	-
123	Aranamanai pudur	AGAMT ooranie	2.00	No		-	-	-	Good	-
124	Dharmapuri	South Theppam	6	No		-	-	-	Good	-
125	Dharmapuri	Karungulam (AGAMT)	10.09	No		-	-	-	Good	-
126	Dharmapuri	Veeranna Gounder Kulam	6.59	No		-	-	-	Good	-
127	Dharmapuri	Graama Theppam	2	No		-	-	-	Good	-
128	Dharmapuri	Kannimar Kulam	1.75	No		-	-	-	Good	-
129	Dharmapuri	Sengulam	1.17	No		-	-	-	Good	-
130	Dharmapuri	Kattu ooranie	0.87	No		-	-	-	Good	-
131	Dharmapuri	Theppam ooranie	0.25	No		-	-	-	Good	-

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
132	Govindanagaram	Vannan ooranie (AGAMT)	10.48	No		-	-	-	Good	-
133	Jangalpatty	Jangalpatti ooranie (AGAMT)	0.15	No		-	-	-	Good	-
134	Jangalpatty	Chettiyar ooranie	0.63	No		-	-	-	Good	-
135	Jangalpatty	Vannan ooranie	0.13	No		-	-	-	Good	-
136	Jangalpatty @ Solaithevanpatti	Thevar ooranie	0.34	No		-	-	-	Good	-
137	Jangalpatty @ Narayanapuram	Subramani chetti ooranie	4.83	Yes		Water Stagnent and murungai tree 30cnt	Action is taken Being	Action is taken Being	Good	-
138	Kattunaickanpatti	Small ooranie	0.2	No		-	-	-	Good	-
139	Kattunaickanpatti	Shenbagam ooranie (AGAMT)	0.5	No		-	-	-	Good	-
140	Kattunaickanpatti	Othu kanmai	0.92	No		-	-	-	Good	-
141	Kattunaickanpatti	Thoppulan Goundan ooranie	4.4	No		-	-	-	Good	-
142	Kattunaickanpatti	Konari ooranie	1.09	No		-	-	-	Good	-
143	Kattunaickanpatti	Karuppan ooranie	2.2	No		-	-	-	Good	-
144	Kattunaickanpatti	Vathiyar ooranie	1.64	No		-	-	-	Good	-
145	Kattunaickanpatti	Pinna thevar ooranie	2.1	No		-	-	-	Good	-

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
146	Kattunaickanpatti	Mottiyasamy Kanmai	1.85	Yes		Karuvel tree Mottiyasamy temple consturctor	Action is taken Being	Action is taken Being	Good	-
147	Koduvilarpatti	Mandhai ooranie	2.25	Yes		water stagnant and Navathanaiyam cultivated	Action is taken Being	Action is taken Being	Good	-
148	Koduvilarpatti	ooranie (AGAMT)	0.31	No		-	-	-	Good	-
149	Koduvilarpatti	Odai ooranie	0.93	No		-	-	-	Good	-
150	Kottur	Veerachinnamal ooranie	0.5	No		-	-	-	Good	-
151	Kottur	Kolikulam ooranie	3.47	No		-	-	-	Good	-
152	Kottur	Eta kudumban Kulam	1.44	No		-	-	-	Good	-
153	Kottur	Puchi Kulam	1.23	No		-	-	-	Good	-
154	Kottur	Vandi Ravuthar Kulam (AGAMT)	1.45	No		-	-	-	Good	-
155	Kottur	Arasi Kulam	1.58	No		-	-	-	Good	-
156	Kuppinaickanpatti	Jakkamal ooranie	2.43	No		-	-	-	Good	-
157	Kuppinaickanpatti	Kuppinaickanpatti Natham (AGAMT)	0.9	No		-	-	-	Good	-
158	Kuppinaickanpatti	Pudhu ooranie	0.52	No		-	-	-	Good	-
159	Nagalapuram	Chetty ooranie	1.96	No		-	-	-	Good	-
160	Nagalapuram	Mayana ooranie	1.29	No		-	-	-	Good	-

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
161	Nagalapuram @ Balakrishna puram	Natham ooranie	3.45	No		-	-	-	Good	-
162	Nagalapuram @ Balakrishna puram	Balakrishnapuram ooranie	6.02	No		-	-	-	Good	-
163	Nagalapuram @ Gopalapuram	ooranie	1.3	Yes		water stagnant and kannimar kovil constructed	Action is taken Being	Action is taken Being	Good	-
164	Poomalaikundu	Oonan Kulam	3.44	No		-	-	-	Good	-
165	Poomalaikundu	Sikkiya Goundar kulam	6.24	No		-	-	-	Good	-
166	Poomalaikundu	Chetti ooranie	0.96	No		-	-	-	Good	-
167	Poomalaikundu	Kaatu ooranie	0.5	No		-	-	-	Good	-
168	Poomalaikundu	Kuda kulam	2.98	No		-	-	-	Good	-
169	Poomalaikundu	Sikkiya goundan kulam	4.65	No		-	-	-	Good	-
170	Poomalaikundu	Bodi Sikkaya Goundar Kulam (AGAMT)	2.61	No		-	-	-	Good	-
171	Poomalaikundu	Pudhu ooranie	2.1	No		-	-	-	Good	-
172	Seelayampatti	Kudumban Kulam (AGAMT)	1.58	No		-	-	-	Good	-
173	Seelayampatti	Veerapa naicken kulam	0.3	No		-	-	-	Good	-
174	Sriengapuram	Natham ooranie	0.26	Yes		Water Stagnent and aari	Action is taken Being	Action is taken Being	Good	-
175	Sriengapuram	AGAMT Kulam	1.00	No		-	-	-	Good	-
176	Thadicheri	Nilaviyal ooranie	0.52	No		-	-	-	Good	-

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
177	Thadicheri	Kutai ooranie	0.67	No		-	-	-	Good	-
178	Thadicheri	Dharmathu ooranie	0.76	No		-	-	-	Good	-
179	Thadicheri	AGAMT Kulam	1.00	No		-	-	-	Good	-
180	Thappukundu	Perumal Goundar ooranie	0.7	No		-	-	-	Good	-
181	Thappukundu	Arasamarathu ooranie (AGAMT)	0.8	No		-	-	-	Good	-
182	Unjampatti	Andal Oorani	0.55	No		-	-	-	Good	-
183	Unjampatti	Kolapparama goundar Oorani	5.6	No		-	-	-	Good	-
184	Unjampatti	Thevakanmai Oorani (AGAMT)	1.22	No		-	-	-	Good	-
185	Upparpatti	ooranie	0.05	No		-	-	-	Good	-
186	Upparpatti	AGAMT ooranie	0.04	No		-	-	-	Good	-
187	Venkatachala puram	Chenniayappa Goundar Oorani	1.22	No		-	-	-	Good	-
188	Venkatachala puram	Jakkamal Kulam (AGAMT)	6.00	No		-	-	-	Good	-
189	Venkatachala puram	Vannan kulam	7.63	No		-	-	-	Good	-
Bodinayakkanur Blcok										
190	Agamalai	AGAMT Kulam Agamalai	0.00.54	No	-	-	-	-	Good	-
191	Ammapatty	Vairavan kanmai	7.82.50	No	-	-	-	-	Good	-
192	Ammapatty	Ammapatty kanmai	2.74.50	No	-	-	-	-	Good	-
193	Ammapatty	Periyaveetarkamm ai	03.20.10	No	-	-	-	-	Good	-

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
194	Ammapatty	Pudhukulam	04.20.10	No	-	-	-	-	Good	-
195	Ammapatty	Palandi kanmai	0.45.5	No	-	-	-	-	Good	-
196	Anaikaraipatty	AGAMT kulam	0.09.50	No	-	-	-	-	Good	-
197	Anaikaraipatty	Uthamparai Kulam	1.40.18	No	-	-	-	-	Good	-
198	Dombuchery	Nagamalayan kanmai	3.80.50	No	-	-	-	-	Good	-
199	Dombuchery	Chinaiyagoundan kulam	15.99.0	No	-	-	-	-	Good	-
200	Dombuchery	Bojigoundan kulam	3.58.0	No	-	-	-	-	Good	-
201	Dombuchery	Vannan Oorani	2.21.0	No	-	-	-	-	Good	-
202	Kamarajapuram	AGAMT kulam	1.05	No	-	-	-	-	Good	-
203	Kodangipatty	Vadathai kulam	1.06.00	No	-	-	-	-	Good	-
204	Kodangipatty	Pannai kedangu	3.04.50	No	-	-	-	-	Good	-
205	Kottakudi	Rasimalai AGAMT	0.45.20	No	-	-	-	-	Good	-
206	Koolayanur	Mallingarswamy kulam	1.22	No	-	-	-	-	Good	-
207	Koolayanur	AGAMT kulam	0.92.8	No	-	-	-	-	Good	-
208	Maniyampatti	Sappani Oorani	17.13.5	No	-	-	-	-	Good	-
209	Maniyampatti	Puthukulam	16.11.00	No	-	-	-	-	Good	-
210	Maniyampatti	AGAMT	2.90.00	No	-	-	-	-	Good	-
211	Maniyampatti	Kadankaran kulam	7.73.33	No	-	-	-	-	Good	-

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
212	Manjinayakanpatti	AGAMT kulam	0.68.6	No	-	-	-	-	Good	-
213	Manjinayakanpatti	Kunjumuppar Oorani	0.92.50	No	-	-	-	-	Good	-
214	Manjinayakanpatti	Muthuveeran kanmai	1.83.50	No	-	-	-	-	Good	-
215	Manjinayakanpatti	Karuppayur Oorani	1.35.00	No	-	-	-	-	Good	-
216	Nagalapuram	Oorani kulam	6.10.00	No	-	-	-	-	Good	-
217	Nagalapuram	Sukkumalli kulam	2.8.00	No	-	-	-	-	Good	-
218	Nagalapuram	Poosari kulam	5.17.50	No	-	-	-	-	Good	-
219	Nagalapuram	Dharma kinaru kulam	1.41.00	No	-	-	-	-	Good	-
220	Nagalapuram	Samuthaya kulam	4.10.00	No	-	-	-	-	Good	-
221	Nagalapuram	Pudukulam	3.2.00	No	-	-	-	-	Good	-
222	Rasingapuram	Koundankulam	5.17.00	Yes	1.00	Agriculture			Needs repair	
223	Rasingapuram	AGAMT kulam	0.45.2	No	-	-	-	-	Good	-
224	Silamalai	AGAMT Soolapuram	0.60.5	No	-	-	-	-	Good	-
225	Silamalai	Vathiyan kulam	8.03.00	No	-	-	-	-	Good	-
226	Silamalai	kurunjiyappar kanmai	3.88.50	No	-	-	-	-	Good	-
227	Silamalai	Soolapuram kanmai	83.88.50	No	-	-	-	-	Good	-
228	Sillamarathupatti	Veeramallammal kulam	2.01.50	No	-	-	-	-	Good	-

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
229	Sillamarathupatti	AGAMT Pudukulam	0.56.5	No	-	-	-	-	Good	-
230	Uppukottai	Kundalnayakkanpatty kulam	0.99	No	-	-	-	-	Good	-
231	Uppukottai	Rowther kulam	1.05	No	-	-	-	-	Good	-
	Chinnamanur Blcok									
		MI Tank								
232	Eranampatty	Kottukarankulam	0.04	No	Nil	Nil	Nil	Nil	Good	
233	Sangarapuram	Vembakottai kulam	0.61	No	Nil	Nil	Nil	Nil	Good	
234	Alagapuri	Pulloranikulam	3.74	No	Nil	Nil	Nil	Nil	Good	
235	Alagapuri	Irulandikulam	0.11	No	Nil	Nil	Nil	Nil	Good	
236	Muthulapuram	Periyankulam kanmai	4.10	No	Nil	Nil	Nil	Nil	Good	
237	Veppampatty	Thadikarankulam	2.02	No	Nil	Nil	Nil	Nil	Good	
238	Veppampatty	Kulasekaran kulam	0.72	No	Nil	Nil	Nil	Nil	Good	
		Pond/Oorani								
239	Alagapuri	Uppukulam	1.02	No	Nil	Nil	Nil	Nil	Good	
240	Alagapuri	Thottan Oorani	0.5	No	Nil	Nil	Nil	Nil	Good	
241	Alagapuri	Kannyangounder Oorani	0.58	No	Nil	Nil	Nil	Nil	Good	
242	Alagapuri	Karichipati Oorani	2.68	No	Nil	Nil	Nil	Nil	Good	

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
243	Alagapuri	Appipatti Oorani	0.12	No	Nil	Nil	Nil	Nil	Good	
244	Ayyampatti	Ayyampatti East Oorani	0.33	No	Nil	Nil	Nil	Nil	Good	
245	Ayyampatti	Ayyampatti East Oorani	0.94	No	Nil	Nil	Nil	Nil	Good	
246	Chinnaovalapuram	Ellaikalkulam	0.85	No	Nil	Nil	Nil	Nil	Good	
247	Chinnaovalapuram	Subbiahgounder kulam	0.62	No	Nil	Nil	Nil	Nil	Good	
248	Chinnaovalapuram	Muthan kulam	0.55	No	Nil	Nil	Nil	Nil	Good	
249	Chinnaovalapuram	Periyakaruppan kulam	0.95	No	Nil	Nil	Nil	Nil	Good	
250	Chinnaovalapuram	Manthai Kulam	1.15	No	Nil	Nil	Nil	Nil	Good	
251	Chinnaovalapuram	Chengulam	1.185	Yes	1.185	Agri	28.11.2018	-	Good	
252	Eranampatty	Solaimalaranaikan kulam	2.45	No	Nil	Nil	Nil	Nil	Good	
253	Eranampatty	Anayanpalanichetty oorani	1.64	No	Nil	Nil	Nil	Nil	Good	
254	Erasakkanaickanur	Kalki Kulam	0.635	No	Nil	Nil	Nil	Nil	Good	
255	Erasakkanaickanur	Chitrakonar Kanmai	3.335	No	Nil	Nil	Nil	Nil	Good	
256	Erasakkanaickanur	Manthai Oorani	0.7913	No	Nil	Nil	Nil	Nil	Good	
257	Kamachipuram	Nattanmaikarar kulam	4.14	No	Nil	Nil	Nil	Nil	Good	
258	Kamachipuram	oorani	0.415	No	Nil	Nil	Nil	Nil	Good	
259	Kamachipuram	Pottal Kulam	2.555	No	Nil	Nil	Nil	Nil	Good	

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
260	Kamachipuram	Alamarathu Oorani	3.435	No	Nil	Nil	Nil	Nil	Good	
261	Kamachipuram	Chikkamanaikayes orani	4	No	Nil	Nil	Nil	Nil	Good	
262	Kaniservaipatti	Vannan Oorani	1.53	No	Nil	Nil	Nil	Nil	Good	
263	Kaniservaipatti	Vannan Oorani	0.345	No	Nil	Nil	Nil	Nil	Good	
264	Kaniservaipatti	Sathukoil Oorani	0.22	No	Nil	Nil	Nil	Nil	Good	
265	Muthulapuram	Vannan Oorani	0.245	Yes	1 Cent	Agri	10.10.2018	-	Good	
266	Muthulapuram	Eswarankovil oorani	0.5	No	Nil	Nil	Nil	Nil	Good	
267	Muthulapuram	Kanniyampatti theppam	0.24	No	Nil	Nil	Nil	Nil	Good	
268	Muthulapuram	Itchikulam kanmai	0.32	Yes	3 Cent	Agri	10.10.2018	-	Good	
269	Muthulapuram	Manthai oorani	0.5	No	Nil	Nil	Nil	Nil	Good	
270	Pottipuram	Pottalkulam	2	No	Nil	Nil	Nil	Nil	Good	
271	Pottipuram	Usilan Kulam	2.26	No	Nil	Nil	Nil	Nil	Good	
272	Pottipuram	Kamaraj Booplala samudram	52.69	Yes	5 Hectare	Agri	28.11.2018	-	Good	
273	Pottipuram	Kottaikulam	1	No	Nil	Nil	Nil	Nil	Good	
274	Pottipuram	Durgaiyammankulam	4.15	No	Nil	Nil	Nil	Nil	Good	
275	Pottipuram	Kottabomman Kanmai	5.12	No	Nil	Nil	Nil	Nil	Good	

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
276	Pulikuthi	Mayilvanan Oorani	0.78	No	Nil	Nil	Nil	Nil	Good	
277	Pulikuthi	Manthai Oorani	2.95	No	Nil	Nil	Nil	Nil	Good	
278	Pulikuthi	Araliyoothu kanmai	0.53	No	Nil	Nil	Nil	Nil	Good	
279	Pulikuthi	Puthu Kulam Oorani	1.665	No	Nil	Nil	Nil	Nil	Good	
280	Pulikuthi	Athimarathu Oorani	2.25	No	Nil	Nil	Nil	Nil	Good	
281	Sankarapuram	Goundarkanmai	0.825	No	Nil	Nil	Nil	Nil	Good	
282	Sankarapuram	Vinayakar Kovil Oorani	0.485	No	Nil	Nil	Nil	Nil	Good	
283	Sankarapuram	Sethugounder kulam	1.875	No	Nil	Nil	Nil	Nil	Good	
284	Sankarapuram	Panaimarathukulam	1.505	No	Nil	Nil	Nil	Nil	Good	
285	Sankarapuram	Kangani kulam	1.205	No	Nil	Nil	Nil	Nil	Good	
286	Sankarapuram	Anjappayesorani	0.2	No	Nil	Nil	Nil	Nil	Good	
287	Sankarapuram	Chinnammaloorani	1.07	No	Nil	Nil	Nil	Nil	Good	
288	Sankarapuram	Vallavan kulam	1.255	No	Nil	Nil	Nil	Nil	Good	
289	Sankarapuram	Sangaralingachetti yaar oorani	0.99	No	Nil	Nil	Nil	Nil	Good	
290	Sankarapuram	Veerapathiran oorani	0.84	No	Nil	Nil	Nil	Nil	Good	

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
291	Seepalakottai	Vedan kulam	3.695	Fully Encroachment	3.695	Agri	24.10.2018	-	Good	
292	Seepalakottai	Kitchmanickan Oorani	1.24	No	Nil	Nil	Nil	Nil	Good	
293	Seepalakottai	Kallpatti Kulam	0.635	No	Nil	Nil	Nil	Nil	Good	
294	Seepalakottai	oorani	0.865	No	Nil	Nil	Nil	Nil	Good	
295	Seepalakottai	oorani	0.885	No	Nil	Nil	Nil	Nil	Good	
296	Seepalakottai	oorani	1.395	No	Nil	Nil	Nil	Nil	Good	
297	Seepalakottai	oorani	0.16	No	Nil	Nil	Nil	Nil	Good	
298	Seepalakottai	oorani	0.305	No	Nil	Nil	Nil	Nil	Good	
299	Seepalakottai	oorani	1.47	No	Nil	Nil	Nil	Nil	Good	
300	Seepalakottai	oorani	0.925	No	Nil	Nil	Nil	Nil	Good	
301	Seepalakottai	oorani	0.225	No	Nil	Nil	Nil	Nil	Good	
302	Seepalakottai	Ellammal Kulam	3.705	No	Nil	Nil	Nil	Nil	Good	
303	Seepalakottai	Puthu Kulam	0.605	No	Nil	Nil	Nil	Nil	Good	
304	Seepalakottai	Puthu kulam	4.255	No	Nil	Nil	Nil	Nil	Good	
305	Seepalakottai	Ponrasu Kulam	2.09	No	Nil	Nil	Nil	Nil	Good	
306	Veppampatti	Pudhukulam kanmai	0.72	No	Nil	Nil	Nil	Nil	Good	
307	Veppampatti	Durairaj kanmai	0.49	No	Nil	Nil	Nil	Nil	Good	

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
308	Veppampatti	Karattu kulam	0.4	No	Nil	Nil	Nil	Nil	Good	
309	Veppampatti	Ooni kanmai	0.9	No	Nil	Nil	Nil	Nil	Good	
310	Veppampatti	Nallukundu Oorani	2.1	No	Nil	Nil	Nil	Nil	Good	
311	Veppampatti	Thasaiyagounder Oorani	0.99	No	Nil	Nil	Nil	Nil	Good	
312	Veppampatti	Sengulam	1.2	No	Nil	Nil	Nil	Nil	Good	
Uthamapalayam Blcok										
313	Anaimalaiyanpatti	Thudaiyagoundankulam	0.67.5	No	-	-	-	-	Good	-
314	Anaimalaiyanpatti	Tannasikulam	22.50	No	-	-	-	-	Good	-
315	Nagayagoundanpatty	Salakal oorani	0.14	No	-	-	-	-	Good	-
316	Nagayagoundanpatty	Kannimar oorani	0.27	No	-	-	-	-	Good	-
317	Nagayagoundanpatty	Anaipatty oorani	0.17	No	-	-	-	-	Good	-
318	Royappanpatty	Achan kulam	0.31.5	No	-	-	-	-	Good	-
319	Royappanpatty	Ramasamynaicken patti Pond	0.16	No	-	-	-	-	Good	-
320	Pallavarayanpatty	Kullamachankulam	14.73.5	No	-	-	-	-	Good	-
321	Pallavarayanpatty	Thathankulam	11.27	No	-	-	-	-	Good	-
322	Pallavarayanpatty	Sakkaiyagoundankulam	6.74	No	-	-	-	-	Good	-

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
323	Pallavarayanpatty	Chettykulam	19.63	No	-	-	-	-	Good	-
324	Pallavarayanpatty	Kamatchikulam @ Sankappankulam	7.40	No	-	-	-	-	Good	-
325	T.Sindalaicherry	Karisalkulam	8.83	No	-	-	-	-	Deepening	-
326	T.Sindalaicherry	Arasamarathukulam	14.95	No	-	-	-	-	Good	-
327	T.Sindalaicherry	Nallukulam	8.92	No	-	-	-	-	Good	-
328	T. Meenakshipuram	Thirumaligoundankulam (Pannaipuram)	12.79	Yes	0.30.50	Coconut Trees	20.09.18	Notice issued on 29.08.18	Good	-
329	T. Meenakshipuram	Odaikulam (Attukarankulam)	1.37	Yes	1	Corn flower, Tomato	20.09.18	Notice issued on 29.08.18	Good	-
330	T. Meenakshipuram	Alagarchettykulam	9.70	No	-	-	-	-	Good	-
331	T. Meenakshipuram	Alagarnaickankulam	11.29	No	-	-	-	-	Needs repair	-
332	T. Meenakshipuram	Sannasinaickankulam	1.45	No	-	-	-	-	Good	-
333	T. Meenakshipuram	T.Mettupatty Orani	1.00	No	-	-	-	-	Good	-
334	T.Renganathapuram	Chinnadevikulam	26.58	No	-	-	-	-	Good	-
335	Thamminaickanpatty	Ganapathychettykulam	3.92.5	No	-	-	-	-	Needs repair	-
336	Thamminaickanpatty	Kurumbankulam	0.92	No	-	-	-	-	Good	-

Sl. No	Location	Name of tank	Extent	Does it have Encroachment	Extent of Encroachment in Hec	Nature of encroachment	Date by when encroachment will be removed	Present stage of action in eviction action	Strength of bund (Good/needs repairs / to be checked)	Date by which repair will be completed
337	Thamminaickanpatty	Perinaickankulam (AGAMT Kulam)	2.50	No	-	-	-	-	Needs repair	-
338	Lakshminaickenpatti	Palanichettykulam	6.91	No	-	-	-	-	Good	-
339	Lakshminaickenpatti	Vannan Orani	5.02	Yes	1	Cornflower	Court Case Pending Dist.Court, Bodi Case.No.45/16		Good	-
340	Lakshminaickenpatti	Thimminaickankulam (Krishnampatty)	5.90	No	-	-	-	-	Good	-
341	Lakshminaickenpatti	Masanam Kanmai (Lakshminaickenpatti)	2.38.5	No	-	-	-	-	Good	-
Cumbum Blcok										
342	Angoorpalayam Panchayat (Cumbum revenue village)	Sikkalikulam	2.03.0	Yes	0.83.0	Fencing / Tamarind tree	30.09.2018	Notice to be issued to 8 encroachers	Needs to be strengthening the Bund	30.10.18
343	Kullappagoundanpatty panchayat (Indira nagar Gudalur east revenue village)	Jeevaganathi Kulam	6.09.0	No	No	No	No	No	Good	No
344	Kullappagoundanpatty panchayat(Indira nagar Gudalur east revenue village)	Kadaman kulam	5.09.0	Yes	0.44.00	Cashewnut trees	15.10.2018	Notice to be issued	Needs to be strengthening the Bund	15.11.18