

**Following CRZ inspection Reports placed before DLC meeting held on 01/09/2021.**

**CANACONA TALUKA**

**ANNEXURE "A"**

<b>Sr. No</b>	<b>Name of the Complainant</b>	<b>Name of the Violator</b>	<b>Sy. No/Village</b>	<b>Nature of alleged violation</b>	<b>Nature of the structure</b>	<b>Approval/ NOC's issued by any other Depts/ Authorities</b>	<b>Nature of Violations if any, with regards to provision of CRZ notification</b>	<b>Whether the proposed construction meet the CZMP</b>	<b>Conclusion/ Recommendation of TLC</b>	<b>DLC Decision</b>
1.	2.	3.	4.	5.	6.	7.	8.	9.	10	11.
1.	Milan Ulhas Pagi	Jaiprakash Ratnakar Pagi	132/10 Nagarcem-Palolem	Construction of RCC Structure	RCC frame Structure Plinth area is 56.05sq.mts	No approval produced	Illegal construction within 500 mtrs.  Distance from the HTL of river/sea 253.80mts	No.	Illegal construction Not to block traditional access or not to construct compound wall ,keep open traditional access and pathway	Decided to forward to GCZMA with recommendation to demolish the illegal construction, as mentioned in column no. 6
2.	Talathi of nagarcem-Palolem	Dayanand Ganesh Pagi	118/1-of village Palolem	Construction of Staircase	Constructed staircases	No	Illegal construction of staircase within 200 mtrs of HTL	No.	Illegal construction of Staircase	Decided to forward to GCZMA with recommendation to demolish the illegal construction of staircase as mentioned in column no. 8

Sr. No	Name of the Complainant	Name of the Violator	Sy. No/Village	Nature of alleged violation	Nature of the structure	Approval/NOC's issued by any other Depts/ Authorities	Nature of Violations if any, with regards to provision of CRZ notification	Whether the proposed construction meet the CZMP	Conclusion/ Recommendation of TLC	DLC Decision
1	2	3	4	5	6	7	8	9	10	11
3.	Premanand Ganesh Naik & Pradeep Kale	Mangala Nagesh Dessai	84/8-A-1 Nagarcem-Palolem	No structure has been constructed	N.A.	N.A.	NA	N.A.	Removed before inspection	As mentioned in column 10, that structure was removed before inspection day. However it is stated in column 5, that no structure has been constructed. It was clarified in the meeting that the structure has been removed. Since the structure does not exist, the proposal is forwarded to GCZMA with a request to direct to maintain the status quo
4.	Talathi of Nagarcem-Palolem	Sandeep Vernekar	104/13-B	Construction of pucca Compound wall	Masonry structure(plinth area is 45.05 sq.mts) Compound wall(plinth area is 24.70sq.mts) Height is 2050m	No.	Within 500 mtrs of HTL	No.	Illegal construction within 500 mts of HTL	Decided to forward to GCZMA with recommendation to demolish the illegal construction as mentioned in column no. 6

Sr. No	Name of the Complainant	Name of the Violator	Sy. No/Village	Nature of alleged violation	Nature of the structure	Approval/NO C's issued by any other Depts/ Authorities	Nature of Violations if any, with regards to provision of CRZ notification	Whether the proposed construction meet the CZMP	Conclusion/ Recommendation of TLC	DLC Decision
1	2	3	4	5	6	7	8	9	10	11
5.	Chadrakant Kusta Pagui	Prakash KustaPagi	132/15	Construction of RCC Structure	RCC structure (plinth area is 60.37sq.mts 2) Height is 3.0m2 21 sq.mts. illegal construction	No	Within 500 mtrs of HTL	No	Illegal construction 275 mts from sea. Recommended to protect the residential house and the structure of traditional fishermen's	Decided to forward to GCZMA with recommendation to demolish the illegal construction as mentioned in column no. 6
6.	Mayur Khemu Khanconkar	Narayan G. Faldesai	124/9,10, 11	Earth filling and Illegal Construction	03 temporary structures ( plinth area is 239.61 sq.mts)  03 permanent Load bearing structures (plinth area is 79.70sq .mts ) Height is 2.50m2	No.	Within HTL & 200 mts of HTL Distance from the HTL of river /sea :73.50mts and three structures fall partly within HTL	No	Illegal construction- Traditional fields has been blocked by owner and blocked the area of canoe parking of traditional fishermen's. Recommended to clear the access and canoe parking area to carry out the daily fishing activities of traditional fishermen's.	Decided to forward to GCZMA with recommendation to demolish the illegal construction as mentioned in column no. 6

Sr. No.	Name of the Complainant	Name of the Violator	Sy. No/ Village	Nature of alleged violation	Nature of the structure	Approval/ NOC's issued by any other Depts/ Authorities	Nature of Violations if any, with regards to provision of CRZ notification	Whether the proposed construction meet the CZMP	Conclusion/ Recommendation of TLC	DLC Decision
1	2	3	4	5	6	7	8	9	10	11
7.	Ehelwene Cardoz, the villagers of Nuvem, Cola,	Local Residents of Nuvem Paguivaddo	289/1	Construction of jetty within HTL	No construction on site , Height of the structure cannot be ascertained , since same is covered under water and sand	No	illegal construction within HTL	No	Traditional fishermen's are parking their canoes and other related equipments such as net, etc. since ancestor's time.	During the discussion, it was mentioned that the jetty is old, but a new ramp has been constructed, hence the matter is reverted back to TLC to clarify the exact violation along with area and photograph.
8.	Dilkush Narayan Pai	Bernardo Santan Carvalho	36/7	RCC Building G+1 floor - 2 Temporary wooden structures	RCC structure G+ 12 no.s(plinth area is 2106.66sq.mts)  04 Teporary wooden structures(plinth area is 102.85sq.mts) Height is 3.00mt /2.50 mt.	No approval produced	Illegal construction within 200 mts & 500 mts of HTL	No	Illegal construction within 200mts & 500mts of HTL , As per RPG 2021 area is settlement zone	Decided to forward to GCZMA with recommendation to demolish the illegal construction as mentioned in column no. 6
9.	UjwalaVithal Bhosale	Sandeep Vernekar, Urmila Balchandra Pagui, Shamal Omu Pagui	36/9	Illegally constructed compound wall	Load bearing compound wall (plinth area is 224.80 sq.mts) Height is 1.50 mt.	No	Illegally constructed compound wall Within 200 mtrs of HTL	No	Illegal construction of compound wall	Decided to forward to GCZMA with recommendation to demolish the illegal construction of compound wall as mentioned in column no. 6

<b>Sr. No.</b>	<b>Name of the Complainant</b>	<b>Name of the Violator</b>	<b>Sy. No/Village</b>	<b>Nature of alleged violation</b>	<b>Nature of the structure</b>	<b>Approval/ NOC's issued by any other Depts/ Authorities</b>	<b>Nature of Violations if any, with regards to provision of CRZ notification</b>	<b>Whether the proposed construction meet the CZMP</b>	<b>Conclusion/ Recommendation of TLC</b>	<b>DLC Decision</b>
<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>	<b>11</b>
10.	Putu Raghoba Pagui, Santosh RaghobaPagui	Shailesh Sudhakar Pagi	80/1	Temporary wooden structure	08 Temporary wooden structures(plinth area is 270.72 sq.mts 2) Height is 2.50mt	Approvals produced by Violator for built up area of 232.32 sq. mtrs of GCZMA dated 10/03/2021	Violator constructed huts in excess area of 40.4 sq. mtrs Distance from HTL of river/sea:80.50mts	No. with respect to the violator the construction in an excess area of 40.4 sq. mtrs	Violator illegally constructed temporary structures in an excess area admeasuring 40.4 sq. mtrs	Decided to forward to GCZMA with recommendation to demolish illegally constructed huts in excess area of 40.4 sq. mtrs distance from HTL of river/sea is 80.50mts.
11.	Prasad NaikGaonkar	Prashant Kanconkar	80/1	Erection of temporary structure	03 Temporary Structure wooden(plinth area is 237.71sq.mts) Height is 2.50mt	Approval granted by GCZMA on dated 16/01/20 for shack and huts of 270 sq. mtrs. For 5 years	Erection of temporary structure	NA	Structure within 200 mtrs of HTL with permission from GCZMA & GSPCB(Encl)	Since no violation has been noticed by the TLC, Canacona at the time of site inspection, hence recommended to be dropped.

**Following CRZ inspection Reports placed before DLC meeting held on 01/09/2021.**

**ANNEXURE "A"**

**SALCETE TALUKA**

<b>Sr. No.</b>	<b>Name of the Complainant</b>	<b>Name of the Violator</b>	<b>Sy. No/Village</b>	<b>Nature of alleged violation</b>	<b>Nature of the structure</b>	<b>Approval/N OC's issued by any other Depts/ Authorities</b>	<b>Nature of Violations if any, with regards to provision of CRZ notification</b>	<b>Whether the proposed construction meet the CZMP</b>	<b>Conclusion/ Recommendation of TLC</b>	<b>DLC Decision</b>
<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>	<b>11</b>
1	Secretary of colva civic-&consumer forum colva salcete-Goa	Not mentioned	28/1 Sernabatim	Demolition of sand dunes	No structure	No documents provided	Alleged demolition of sand dunes to construct road	There is no sign of any demolition of pioneer sand dunes due to construction of road	Recommended to be dropped. During the site inspection it was noticed that there was no sign of any demolition of sand dunes within 50mts of HTL to construct illegal road in sy.no. 28/1 sernabatim	During the site inspection it was noticed by the TLC, Salcete , that there was no sign of any demolition of sand dunes within 50mts of HTL to construct illegal road in sy.no. 28/1 sernabatim Hence, recommended to be dropped
2	Jovek Cardozo	Berth fernandes & Camilo fernandes	17/9 &16/2 sernabatim	Illegal construction	Illegal construction (details of structures attached Annexure A)	_ Not produced by the owner	Illegal construction	Since no documents are provided by the owner ,it seems to violation of CZMP guideline	As per the Regional plan 2021 for Goa the property under sy.no. 16/2 of senabatim is earmarked as partly settlement zone and partly cultivable land and survey no.17/9 of sernabatim is earmarked as settlement zone. Hence recommended for demolition	Decided to forward to GCZMA with recommendation to demolish the illegal construction , as mentioned in column no. 6

<b>Sr. No.</b>	<b>Name of the Complainant</b>	<b>Name of the Violator</b>	<b>Sy. No/Village</b>	<b>Nature of alleged violation</b>	<b>Nature of the structure</b>	<b>Approval/NOC's issued by any other Depts/ Authorities</b>	<b>Nature of Violations if any, with regards to provision of CRZ notification</b>	<b>Whether the proposed construction meet the CZMP</b>	<b>Conclusion/ Recommendation of TLC</b>	<b>DLC Decision</b>
<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>	<b>11</b>
3	Agnelo Noronha	Sergio Dias & Jerson Rebelo.	54/1 uttorda	Illegal soak pit/ septic tank/ cutting natural vegetation/ cutting sand dunes and filling sand bag/ fencing the property	06 Temporary structures , plinth area of the structure's is 1964.64 sq.mts	Approved plan from GCZMA for retaining wall & filling NOC from GCZMA for construction of laterite retaining wall , NOC from WRD for constant of retaining wall ,RIT from GCZMA, NOC from TCP for filling of land Approved shack plan & wooden fencing from GCZMA. panchayat NOC for shack.	Build up area exceeds approved limit beyond 186.80 sq.mts m2	No	As per the regional plan 2021 for Goa the property under sy.no. 54/1 of utorda is earmarked as partly orchard zone and settlement zone. Hence recommended for demolition of excess area	Decided to forward to GCZMA with recommendation to demolish excess area beyond 186.80 sq.mts , as mentioned in column 8

<b>Sr. No.</b>	<b>Name of the Complainant</b>	<b>Name of the Violator</b>	<b>Sy. No/Village</b>	<b>Nature of alleged violation</b>	<b>Nature of the structure</b>	<b>Approval/NOC's issued by any other Depts/ Authorities</b>	<b>Nature of Violations if any, with regards to provision of CRZ notification</b>	<b>Whether the proposed construction meet the CZMP</b>	<b>Conclusion/ Recommendation of TLC</b>	<b>DLC Decision</b>
<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>	<b>11</b>
4.	Secretary of colva civic & consumer forum colva salcete	Not mentioned	Sy.no. 8/1, 9/1 sernabati m salcete	Demolition of sand dunes , cutting of tress, construction of illegal road	No structure	No document provided	Only kutchra road in sy no 9/1 and some bushes are cut and dumping of construction debris. No activity seen in sy no 8/1	Since complainant remained absent the exact location of demolition of 6mts to 8mts tall sand dunes could not be located on site	To be dropped. Complainant as well as respondent not present for the site inspection, hence height and location could not be ascertained	As per the attached photo clicked , It is seen that kutchra road is being constructed by cutting of trees , however during the time of site inspection the Complainant as well as respondent were not present, hence height and location could not be ascertained. Hence decided to refer back to forest Dept. for re-inspection to ascertain fact. Hence, decided to refer to forest Dept. to inquiry into the complaint of cutting of tress



<b>Sr. No.</b>	<b>Name of the Complainant</b>	<b>Name of the Violator</b>	<b>Sy. No/Village</b>	<b>Nature of alleged violation</b>	<b>Nature of the structure</b>	<b>Approval/ NOC's issued by any other Depts/ Authorities</b>	<b>Nature of Violations if any, with regards to provision of CRZ notification</b>	<b>Whether the proposed construction meet the CZMP</b>	<b>Conclusion/ Recommendation of TLC</b>	<b>DLC Decision</b>
<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>	<b>11</b>
5.	Juliana Rebello & Bernadtte Lourdes D'costa	Gregorio & Bruno Fernandez	48/1,47/5,47/23 varca salcete	Illegal constuction in sy.no 48/1,47/5,47/23 varca salcete and polluting water bodies	Load bearing structure covered with Gal vulium roofing sheets on steel frames work Height of the structure is 4.8 mts Plinth area is 125.05 sq.mts	No document provided	No approval from GCZMA produced by the alleged violator	Since no document is provided it seems to violation. The property bearing sy no.48/1 of varca is earmarked as paddy field where structure is erected at site as per R.p of 2021. sy no. 47/1 earmarked as orchard zone and sy no 47/5 is earmarked as paddy field zone as per RP for Goa 2021	Recommended to demolish	Decided to forward to GCZMA with recommendation to demolish illegal construction, as mentioned in column 6
6.	Rocky Caldria	Not mentioned	--- varca salcete	Illegal erection of private shack	No structure seen	No NOC produced	The complainant shri Rocky calderia could not be served as there is no person by that name. The complaint is not specific with regard to the survey numbers in varca beach. Thus the complaint cannot be verified as photo & surveys nos are not attached to the complaint	No construction seen	Recommended to be dropped	During the site inspection, no construction was seen by the TLC, Salcete. Hence decided to forward to GCZMA with recommendation to be dropped

<b>Sr. No.</b>	<b>Name of the Complainant</b>	<b>Name of the Violator</b>	<b>Sy. No/Village</b>	<b>Nature of alleged violation</b>	<b>Nature of the structure</b>	<b>Approval/NOC's issued by any other Depts/ Authorities</b>	<b>Nature of Violations if any, with regards to provision of CRZ notification</b>	<b>Whether the proposed construction meet the CZMP</b>	<b>Conclusion/ Recommendation of TLC</b>	<b>DLC Decision</b>
<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>	<b>11</b>
7.	Oswald Fernandez	Sevana S Jacques	150/3, 4-A, 6, 1-A,, 2, 7, 8, 9, 4, 3/1, 1-A, 2,3 of Cavellosim	-	RCC frame structures , (report enclosed as <b>Annexure " B"</b>	Caste certificate, license to ply vessel, sale deed, house tax of h.no 71  The Chairman of TLC, Salcete vide letter dated 19/8/2021 has informed that under sy. no. 150/4 & 6 of Cavellosim village, permission from relevant authorities are produced by the owner of the restaurant in sy.nos 150/4 & 6 of Cavellosim village	Permissions have been obtained for 50 seater restaurant, STP plant and DG' set. However, no permissions were produced for dance floor in survey no.150/6., which need to be demolished. Also , the structure in sy.no. 3/1-A, which is claimed as fishing infrastructure by the opponent needs to be examined by GCZMA under CRZ rules.	NO	Structures in sy.no. 3/1-A to be protected as it is used for fishing related activities i.e to keep their canoe nets, workers and material and their livelihood etc. hence not recommended	Decided to forward to GCZMA with recommendation to undertake necessary action , as mentioned in column 8.

<b>Sr. No.</b>	<b>Name of the Complainant</b>	<b>Name of the Violator</b>	<b>Sy. No/Village</b>	<b>Nature of alleged violation</b>	<b>Nature of the structure</b>	<b>Approval/NOC's issued by any other Depts/ Authorities</b>	<b>Nature of Violations if any, with regards to provision of CRZ notification</b>	<b>Whether the proposed construction meet the CZMP</b>	<b>Conclusion/ Recommendation of TLC</b>	<b>DLC Decision</b>
<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>	<b>11</b>
8.	Ajay phadke	Club Mahendra beach resort and zuari white sands	Varca Salcete	dumping raw untreated sewage on public property	No structure seen	Test certificate provided	Alleged dumping raw untreated sewage on public property	None noticed	The complaint is pertaining to dumping of raw and sewage on public nalla, there is not outlet in the nalla of sewage is seen, hence T.CP role is not involved	Decided to refer to Pollution Control board to verify raw untreated sewage on public property.
9	Rosarinho M. Fernandez r/o (received from SDO-II)	Not mentioned	335/0 and 338/1 of village veliem	Inspection of all the structures erected of the respondent in sy.no. 335/0 & 338/1	1. RCC frame structure, & partly (height is 3.5m) 2. Loading bearing structures (height is 7.6m)	No approval produced by the defaulter	N.A	No	Please protect traditional fishermen's as well as local community people and their livelihood and to do their fishing activity and fishing business	Since no approval produced by the complainant, hence decided to forward to GCZMA with recommendation to demolish all the structures, as mentioned in column 6

Sr. No.	Name of the Complainant	Name of the Violator	Sy. No/Village	Nature of alleged violation	Nature of the structure	Approval/NOC's issued by any other Depts/ Authorities	Nature of Violations if any, with regards to provision of CRZ notification	Whether the proposed construction meet the CZMP	Conclusion/ Recommendation of TLC	DLC Decision
1	2	3	4	5	6	7	8	9	10	11
10	Norvin Machado	Joao Antonio Fernandez and Agnelo Fernandez	69/1 of Colva village	Illegal construction of shacks in sy.no. 69/1 of Colva	-	-			At the time of inspection, there were no shacks erected in sy.no 69/1 of Colva village , hence complaint is returned back	At the time of site inspection, there were no shacks erected in sy.no 69/1 of Colva village, hence recommended to be dropped
11	Socorro Miranda & others	West coast hotel pvt. Ltd	125/1 varca salcete	Blocking of access to the carmona beach by west coast hotels pvt. Ltd putting up concrete poles with GI fencing in CRZ area.	Structure s Report enclosed - (Annx C) and barbed fencing	No Document submitted	N.A	N.A	Recommended for demolition .The property bearing sy no .125/1 of varca village in earmarked as partly orchard zone and partly settlement zone.	Decided to forward to GCZMA with recommendation to demolish
12	Judas Mercy Rato	Ranjana overseas Pvt. .Ltd, Varca	211/1 (part) Varca Salcete	Illegal conversion and illegal construction .	Structure s Report enclosed (Annx D)	Project was approved by the Member Secretary/GSCC/TCP vide GSCCE/SAL/08/TCP/94/1700 dt.915/94. However structure shown on survey plan prepared by taluka committee are not reflected on approved plan hence it is illegal.	Illegal construction	-	New shed and new structure are illegal and in violation with the approved plan  NOTE ;As per RP 2021 the property bearing as per sy.no. 211/1 (part) is earmarked as settlement zone.	Structures shown in survey and plan prepared by taluka committee are not reflected on approved plan. Hence, decided to refer to TLC with a direction to obtained a details of structures from TCP and PWD.

## REPORT- ANN X A

Sub: complaint against illegal construction in survey No. 17/9 and 16/2 of village sernabatim by Mrs. Bertha Fernandes and Mr. Carmilo Fernandes

Sr.NO	Plinth Area of the structure	Height of the structure	Nature of structure
1:	293.98 sq.m	4.80m	Load bearing structure with manglore tile roof.
2:	4.04sq.m	3.37m	Water tank stand in laterite masonry and RCC slab
3:	4.52sq.m	0.70m from GL	Open well in laterite masonry
4:	75.70sq.m	6.90 m	Permanent structure
5:	2.22sq.m	2.30 m	Wooden walls & floor and AC sheet roof
6(A)	19.00sq.m	3.40 m	Wooden walls & floor and AC sheet roof
6(B)	12.61sq.m	3.30 m	Wooden walls ,PCC floor and manglore tile roof
6(C)	6.63 sq.m	3.30 m	Temporary structure
6(D)	22.04 sq.m	2.63 m	Temporary structure ( cement concrete , floor ,manglore tile roof)
7:	6.13 sq.m	2.20 m	Wooden walls with AC sheet roof and cement concrete floor
8:	185.81 sq.m	8.10( approximate)	Permanent structure
9:	5.26 sq.m	4.00 m	Laterite masonry wall with flat RCC slab
10:	4.32 sq.m	0.50 m from GL	Open well in laterite masonry
11:	18.79 sq.m	4.20 m	Wooden floor and wall and manglore tile roof
12:	3.97 sq.m	2.80 m	Brick masonryv walls

			with RCC roof and ceramic tile flooring
13:	37.69 sq.m	3.25 m	Load bearing structure with Galvalium sheet roof
14(A)	18.88 sq.m	3.70 m	Wooden structure with manglore tile roof and cement concrete flooring
14(B)	60.82 sq.m	3.50 m	Brick masonry walls with manglore tile roof and kotah stone flooring
15:	4.50 sq.m	2.57 m	Wooden structure
16:	3.60 sq.m	2.20 m	Masonry structure
17:	136.60 sq.m	3.20 m	Tempopary structure ( wooden frame structure with tarpaulin on top and inter locking paver flooring )
18:	19.19 sq.m	2.75 m	Masonry structure ( laterite masonry walls , manglore tile and fibre sheet roof and ceramic tile flooring

## REPORT

Sub: Destruction of salt pans and paddy fields in khazan land by dumping mud, construction rock wall and structure illegly in CRZ area of village Cavelossim

### ANNX B

Sr.No	Plinth area of structure	Height of structure	Nature of structure
1:	10.07 sq.m ts	3.50 mts	RCC frame structure
2	8.41 sq.mts	3.30 mts	RCC frame /load bearing structure
3	18.50 sq.mts	2.55 mts	Temporary structure
4	9.92 sq.mts	2.65 mts	Temporary structure
5a	352.21 sq.mts	7.52 sqmts	Steel frame structure with galvulium roof
5b	27.26 sq.mts	3.30sqmts	Masonry structure
5c	145.54 sq.mts	3.12 mts	Temporary structure
5d	123.95 sq.mts	4.17 mts	Temporary structure
5e	20.31 sq.mts	3.45 mts	Masonry structure
6	19.11 sq.mts	4.44 mts	Temporary structure
7	53.08 sq.mts	4.20 mts	Temporary structure
8	22.00 sq.mts	3.25 mts	Masonry structure
9	2.81 sq.mts	9.60 mts	Steel frame structure for resting water tank with galvulium sheet roof
10	45.00 sq.mts	2.83 mts	Temporary structure
11	1.44 sq.mts	2.30 mts	Temporary structure
12	30.32 sq.mts	3.33 mts	Masonry structure
13	43.22 sq.mts	3.95 mts	Masonry structure
14	118.19 sq.mts	3.85 mts	Masonry structure
15	63.42 sq.mts	3.05 mts	Temporary structure
16	53.83 sq.mts	3.85 mts	Temporary structure
17	25.25 sq.mts	2.98 mts	Temporary structure
18	6.48 sq.mt	0.75mt. from ground level	Open sump in laterite masonry without cover

19	9.10sqmt	0.75mt. from ground level	Open sump in laterite masonry without cover
20	-	1.20 mt	SS railing rested on laterite masonry and cement concrete wall ( length 119.40 mts )
21	-	-	Laterite masonry wall rested on cement concrete retaining wall (length 120mts )
22	-	1.60 mts	Compound wall in laterite masonry ( length 40.30mts

## ANNX C

### STRUCTURE REPORT

Sub: - Blocking of the access to the Carmona beach by the west coast hotel Pvt. Ltd by putting up concrete poles withy GI fencing in CRZ area

SR. No.	Plinth area of the structure	Height of the structure	Nature of structure
	<b>Internal</b>		



	<b>Compound</b>		
1.	-	1.30 m	G.I chain link mesh fencing with cement concrete pillar for support at 2.90m (approximate) Centre to Centre. length of fencing is 71.00 m.
2	-	1.80m ( average)	G.I Chain link mesh fencing resting on cement concrete/ laterite masonry wall with vertical cement concrete pillar for support. Length of fencing is 109.00m.
3	-	2.10m	Compound wall in laterite masonry. length of compound wall 20.20 m.
	<b>Sea Facing</b>		
4	-	1.30m	G.I chain link mesh fencing with vertical cement concrete pillar support at 2.00 – 3.00 distance. Length of fencing is 197.60m
	<b>Along the road side</b>		
5	-	1.30m	G.I chain link mesh fencing with vertical cement concrete pillar supported at approximate 2.00 – 3.00 m distance. Length of fencing is 62.60 m.
6	-	2.30m	G.I chain link mesh fencing rested on cement concrete/ laterite masonry wall with vertical cement concrete pillar support for chain link mesh. Length of fencing is 33.30m.
7	-	1.90m	G.I chain link mesh fencing rested on cement concrete/ laterite masonry wall with vertical cement concrete pillar

			support for chain link mesh. Length of fencing is 74.30m.
8	-	2.60	Laterite masonry compound wall. Length of compound wall is 30.70m.

## **REPORT**

### **ANNX D**

#### **STRUCTURE REPORT**

Sub: - Illegal conversion and illegal construction by Ranjana Overseas Pvt. Ltd. In survey no. 211/1 and survey no. 211/1 (part) of village Varca located on Pedda and operation of commercial hotel/ business namely M/s Regenta Resort at the location

Sr. No.	Plinth area of the structure	Height of the structure	Nature of the structure
1	169.06 m2	7.90m	Permanent structure
2	43.56 m2	3.30m	Permanent structure ( Laterite masonry wall, Galvulium sheet roof, cement concrete flooring)

3	104.19 m2	3.90m	Permanent structure ( Fiber sheet roof supported on steel frame structure, vitrified tile flooring)
4	160.00 m2	1.40m	Permanent structure (swimming pool)
5	28.62 m2	3.20m	Permanent structure (Galvulium sheet roof supported on steel frame structure, laterite masonry walls, vitrified tile flooring)
6	287.96	6.90m	Permanent structure
7	3.97	-	Cement concrete ring well