

**CRZ Report of Mormugao Taluka to be placed before DLC on 17/11/2021**

<b>Sr. No</b>	<b>Name of the Complainant</b>	<b>Violator</b>	<b>Sy.no./Village</b>	<b>Nature of alleged violations</b>	<b>Nature of the Structure</b>	<b>Approval/NOC's issued by any other Cepts/Authorities</b>	<b>Nature of Violations if any, with regards to provision of CRZ notification</b>	<b>Whether the proposed construction meet the CZMP guidelines</b>	<b>TLC Conclusion/ Recommendation</b>	<b>DLC decision</b>
<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>	<b>11</b>
1	Fatima D'Cruz & Mr. Manuel D'cruz	Sebliz Superstones	70/5 Chicalim	Illegal Construction comprising of ground floor only	Plinth area 146.79m <sup>2</sup> (as per PWD report ) height is 5.00mtrs	No	Illegal Construction comprising of ground floor only-Distance from HTL is within 200 mts	-No	The construction is carried out illegally comprising of Ground Floor Only.	1. Decided to forward to GCZMA with recommendation to demolish Illegal construction, as mentioned in column no. 8. 2. Also directed to SDO Mormugao to initiate proceeding as per section 33 of LRC 1968 and conclude proceedings in a time bound manner

2	Fatima D'Cruz & Mr. Manuel D'Cruz	Sakaram Restaurant	70/1 Chicalim	Construction comprising of ground floor only	Plinth area of structure 190.06m <sup>2</sup> height of the structure 2.50mtrs	No	Illegally erected structure within 200mts of HTL	No	Illegally erected structure within 200mts of HTL	<p>1. Decided to forward to GCZMA with recommendation to demolish Illegal erected structure , as mentioned in column no. 8.</p> <p>2. Also directed to SDO Mormugao to initiate proceeding as per section 33 of LRC 1968 and conclude proceedings in a time bound manner</p>
---	-----------------------------------	--------------------	---------------	--	--	----	--	----	--	--

3	Fatima D'Cruz & Mr. Manuel D'Cruz	Sarita Guest House	70/1 (Part) Chicalim	Illegal Construction comprising of ground & first floor only and open shed facing beach	RCC frame structure with area 346.20mtrs, height is 6.00mtrs	No	Illegal Construction comprising of ground & first floor only and open shed facing beach- Distance from HTL is within 200 mts	No	The construction is carried out illegally comprising of ground and first floor only and open shed facing beach.	1. Decided to forward to GCZMA with recommendation to demolish Illegal erected structure , as mentioned in column no. 8. 2. Also directed SDO Mormugao to initiate proceeding as per section 33 of LRC 1968 and conclude proceedings in a time bound manner
4	Fatima D'Cruz & Mr. Manuel D'Cruz	Mr. John Seaguls	70/2-A Chicalim	Illegal Construction comprising of ground & open developed area for sitting	RCC frame structure with plinth area is 432.00Sq.mts ,height is 3.50mtrs	No-	Illegal Construction comprising of ground & open developed area for sitting-Distance from HTL is within 200 mts	No	The construction is illegally constructed comprising of Ground Floor and open developed area for sitting	1. Decided to forward to GCZMA with recommendation to demolish Illegal construction, as mentioned in column no. 8. 2. Also directed SDO Mormugao to initiate proceeding as per section 33 of LRC 1968 and conclude

5	Fatima D'Cruz & Mr. Manuel D'Cruz	Mr Victor Alvares	70/2 Chicalim	Illegal Construction comprising of ground floor only	RCC frame structure with plinth area is 180.20m <sup>2</sup> , height is 3.50mts	No	Illegal Construction comprising of ground floor only-Distance from HTL is within 200 mts	No	The structure is constructed illegally within 200mts of HTL	1. Decided to forward to GCZMA with recommendation to demolish Illegal construction , as mentioned in column no. 8. 2. Also directed SDO Mormugao to initiate proceeding as per section 33 of LRC 1968 and conclude proceedings in a time bound manner
6	Ana Severina Gracias	Placida Barretto	14/3 Quelossim	Illegal construction of unauthorised structure.	RCC: 214.00m <sup>2</sup> , height is 4.00mts	No	Illegal construction of unauthorised structure-Distance is within 40 mts	No	The construction is carried out illegally.	Recommended to forward to GCZMA to demolish illegal construction as mentioned in column 8. subject to verification of GCZMA limits w.r.t. Width of river by GCZMA as per its records

7	Sarpanch V.P Quelossim	Movaj Enterprises Pvt Ltd.	170/0 Quelossim	Illegal carrying out of work in Sy. No 170/1 of Village Quelossim	-	No NOC is issued by any authority/ Dept/	Illegal carrying out of work in Sy. No 170/1 of Village Quelossim	No	During the site inspection there was no any work being carried out at the site.	Decided to return back to TLC to re- inspect again and report back in 15 days with photo alongwith checklist
8	Goa Paryavaran Savarakshan Sangarsh Samiti	Raymond Desa	73/3 Cortalim	Illegal work in survey no.73/3	RCC Frame: plinth area is 162.40mts height is 3.60mts	No	Illegal work in survey no.73/3-Distance from HTL is within 100 mts	No	Illegal construction of work carried out in survey no.73/3	Recommended to forward to GCZMA to demolish illegal construction as mentioned in column 10. subject to verification of GCZMA limits w.r.t. Width of river by GCZMA as per its records

9	Ana Maria Fernandes	Mr Bento Vincent	12/14 Velsao	Illegal construction in NDZ & CRZ Area.	Masonry structure plinth area is - 148.06m <sup>2</sup> , RCC frame structure, Plinth area is 124.03m <sup>2</sup> (Ground floor & 1st floor)height is 6.00 mts	No	Illegal construction structure within 200 CRZ area-	No	The construction is carried out illegally in NDZ & CRZ Area.	1.Decided to forward to GCZMA with recommendation to demolish Illegal construction, as mentioned in column no. 8 2.Also directed SDO Mormugao to initiate proceeding as per section 33 of LRC 1968 and conclude proceedings in a time bound manner
10	Aditya Yadav	Unknown Person	Chalta no. 4(Part) PTS No. 18 in Vasco City	Illegal construction of concrete wall and unauthorised structure	Load Bearing structure , plinth area is 51.52m <sup>2</sup> , height is 1.00mts (concret wall)	No	Illegal construction of concrete wall and unauthorised structure.Distance is within 100 mtrs	No	The construction of concret retaining wall and structure is carried out illegally	Decided to return back to TLC to re-inspect again whether it is CRZ - II or III area and also to mentioned the violator name i.e occupant name and report back in

11	Shree Vijayadurga Shankhvali Teerthkshetra Punarnirmaan Samiti C/o. Sachit Naik, H.No.133/1, Near Gomantak Bakery, Sancoale Goa	Parish Priest Louis Alvares	266/2 Sancoale Village.	Erecting illegal structure/pandal within CRZ area	NIL	No	During the Site Inspection no any illegal CRZ violation was seen at the site	No	During the Site Inspection no any illegal CRZ violation was seen at the site	Since no violation has been noticed by the TLC, mormugao at the time of site inspection, hence recommended to be dropped.
12	Chairman, Chicalim Bio-diversity Management Committee, Chicalim Mormugao Goa	Unknown Person	-	Dredging activities in Chicalim bay	-	No	Dredging activities in Chicalim bay	No	During the site inspection there was no any dredging activity at the site.	1.Decided to to forward to WRD and Captain of ports for confirming violation if any and to report to GCZMA , since the complaint pertains to dredging activities

13	Agnelo Rodrigues	Minguelina Goes, Domingo Goes & Alwyn Goes	12-1 pale	Construction of Illegal and unauthorised structure in survey no.12/1 of Velsao Village	RCC Frame structure, plinth area is 115.92m2, height is 3.00mts	No	Construction of Illegal and unauthorised structure in survey no.12/1 of Pale Village- distance is within 200 mt from HTL	No	Illegal and unauthorised structure is carried out in survey no.12/1 of Pale Village	1. Decided to forward to GCZMA with recommendation to demolish Illegal construction, as mentioned in column no. 8 2. Also directed SDO Mormugao to initiate proceeding as per section 33 of LRC 1968 and conclude proceedings in a time bound manner
14	Prashant Vasta, General Secretary of Niz Goenkar Revolution Front	Unknown Person	266/2 Sancoale Village.	Illegal construction of structure within CRZ area	NIL	No	Illegal construction of structure within CRZ area		During the site inspection there was no any structure erected at the site	1. Since no violation has been noticed by the TLC, mormugao at the time of site inspection, hence recommended to be dropped.



15	Fatima D'Cruz & Mr. Manuel D'Cruz	Laxman Kavlekar Shop	57/14 of village chicalim	Illegal construction comprising of Ground floor only	Steel Sheets Side Walls - 26.60m <sup>2</sup> height is 2.50mts	No	Illegal construction comprising of Ground floor only, distance from HTL is beyond 200 mts	No	Illegal construction comprising of Ground floor only	Recommended to forward to GCZMA to demolish illegal construction as mentioned in column 8. subject to verification of GCZMA limits w.r.t. Distance of river by GCZMA as per its records
16	Fatima D'Cruz & Mr. Manuel D'Cruz	Kevin shop	70/5 Chicalim	Illegal Construction of shop with laterite stone masonry and AC sheet roofing	RCC framed structure plinth area is - 31.75 m <sup>2</sup> , height is 4.50mts	No	Illegal Construction of shop with laterite stone masonry and AC sheet roofing, distance is within 200 mts from HTL	No	Illegal Construction of shop with laterite stone masonry and AC sheet roofing	1. Decided to forward to GCZMA with recommendation to demolish Illegal construction, as mentioned in column no. 8 2. Also directed
17	Sandeep Naik	Unknown Persons	-	Illegal construction and illegal activities on beach area Desterowado behind Old MPT hospital		no	Illegal construction and illegal activities on beach area Desterowado behind Old MPT hospital	no	Notice could not be served to the complainant through the talathi of Mormugao saza wherein the talathi has reported that no person by name Sandeep Naik is	Decided to return back to TLC to re-inspect and to verify the location again and report back in 15 days with photo alongwith checklist

18	Fatima D'Cruz & Mr. Manuel D'Cruz	La Petite Guest House	70/1 Chicalim	Illegal Construction of Guest house comprising of ground & first floor only	RCC frame structure - 195 mts, Load bearing - 93.89 mts total plinth area 288.89m <sup>2</sup> , height is 6.50mts	No	Illegal Construction of Guest house comprising of ground & first floor only	No	The construction is carried out illegally of Guest house comprising of Ground and First Floor.	1. Decided to forward to GCZMA with recommendation to demolish Illegal construction, as mentioned in column no. 8. 2. Also directed
19	Shri Stanley Barros Pereira R/o. H.No.28, Opp. Railway Station, Cansaulim Goa	Unknown person	Sy.No.73/3 of Cansaulim	Illegal construction in property bearing survey no.12/1 of Velsao Village	RCC Slab: Plinth area is 7.20m <sup>2</sup>	No	Illegal construction in property bearing survey no.73/3 of Cansaulim Village- distance from HTL is within 200 mts	No	During the site inspection it was seen that RCC slab of 7.20m <sup>2</sup> is constructed on Nallah.	1. Decided to return back to TLC for re-inspection and for obtaining report from WRD and report back in 15 days with photo alongwith checklist

20	Nigel D'Souza	Candelina Fernandes/Parmaz properties	132/4 & 5 Arossim	Construction of illegal and unauthorised fencing of permanent nature	Fencing of barbed wiring with RCC poles at the site	No	Construction of illegal and unauthorised fencing of permanent nature-distance from HTL is within 200 mts	No	Construction of Illegal and unauthorised fencing of barbed wiring with RCC poles carried out at the site of permanent nature	Decided to forward to GCZMA with recommendation to demolish Illegal construction, as mentioned in column no. 8 2.Also directed SDO Mormugao to initiate proceeding as per section 33 of LRC 1968 and conclude proceedings in a time bound manner
21	Fatima D'Cruz & Mr. Manuel D'cruz	Bogmalo Beach Resort	66/5,6,7,8, 73/1 of Chicalim	Illegal Construction of wooden cottages comprising of ground floor only and palm tree cottage bamboo shades and compound	RCC structure - 434 .10m2 b) Load bearing - 220.38 sq.mts C) Temporary structures - 892.49m2, total plinth area is 1546.97m2,	No-	Illegal Construction of wooden cottages comprising of ground floor only and palm tree cottage bamboo shades and compound wall -distance from HTL is within 200 mts	No	Illegal Construction of wooden cottages comprising of ground floor only and palm tree cottage bamboo shades and compound wall	Decided to forward to GCZMA with recommendation to demolish Illegal construction, as mentioned in column no. 8 2.Also directed

22	Vishal Naik(NGT matter)	Mr Suresh Basu Naik	264/5 Sancoale	Illegal construction of commercial and residential structure within 10mts from HTL	Load bearing & Masonary structure, plinth area is 115.50m2, height is 3.10 mts	No-	Illegal construction of commercial and residential structure within 10mts from HTL	No	The construction is carried out illegally comprising of commercial and residential structure.	Decided to forward to GCZMA with recommendation to demolish Illegal construction, as mentioned in column no. 8 2.Also directed SDO Mormugao to initiate proceeding as per section 33 of LRC 1968 and conclude proceedings in a time bound manner
23	Marman Engineering & Shipbuilding	-	Sancoale	Removal of accumulated Softmud/ silt/ Sand deposited by flowing river	-	No	N.A, as this is fresh proposal for obtaining NOC	No	The application is proposal for obtaining NOC from CRZ Authorities for removal of accumulated Softmud/ silt/ Sand deposited by flowing river	1.Decided to forward to WRD and Captain of ports for confirming violation if any and to report to GCZMA , since the complaint pertains to dredging

24	Sunil Batta, beach front resort Pvt. Ltd, Lal kothi scheme tonk road Jaipur	Unknown person	54/1-C Velsao	Illegal construction & blockage of access road in village Velsao	RCC frame structure, plinth area is 5.70mts hight is 1.60mts	No approvals produced	Illegal construction & blockage of access road in village Velsao- within 200mts from HTL	No	New gate is installed with RCC coloum thereby blocking the access road	Decided to return back to TLC to re-inspect again and report back in 15 days with photo alongwith checklist
25	The Chairman, Chicalim bio diversity management committee	Proposed nature resort	148/1,2& 3 Chicalim	....	....	.....	....	....	During the site inspection there was no any illegal construction, nature resort at the site	Since no violation has been noticed by the TLC, mormugao at the time of site inspection, hence recommended to be dropped.
26	Mr. Savio Conrado Colaco, R/o H. No 2/D Castelvaddo Nagoa Salcete	Ms Maria Fernandes	72/2 Velsao	Illegal Construction	Load bearing/ Masonary structure plinth area is 26.62mts, hight is 3.00mts	No	Illegal construction within 200mts from HTL	No	Illegal Construction in property sy no 72/2 of velsao village	Decided to return back to TLC to re-inspect again and report back in 15 days with photo alongwith checklist

27	Sunil Batta, director of beach front resort Pvt. Ltd,	Unknown person/ occupant	54/1-C Velsao	Illegal construction on the beach side in village velsao	Temporory structure, plinth area is 31.90mts, hight is 2.00mts	No approvals produced	Illegal construction on the beach side in village velsao- distance from HTL is within 100mts	No	Illegal structure carried out on beach side carried out in velsao	Decided to forward to GCZMA with recommendation to demolish Illegal construction, as mentioned in column no. 8 2. Also directed SDO Mormugao to initiate proceeding as per section 33 of LRC 1968 and conclude proceedings in a time bound manner
----	--	--------------------------------	------------------	---	---	-----------------------------	--	----	--	--